

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR A910 141693-1837 - Front Right Wheel Hub

Sample No: LH0249756

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90



JOSH LASALLE CONSTRUCTION EQUIPMENT LTD
541 PIONEER RD.
MERRICKVILLE, ON
CA K0G 1N0
Contact: Service Manager



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0249756	LH0249734	---	---
Date d'échant.	02 Nov 2023	26 Jun 2023	---	---
Heures de la Machine	1104	501	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	91.8	80.0	---	---
-----------	-----	------	------	-----	-----



CONTAMINATION

Silicium	ppm	8	13	---	---
Sodium	ppm	2	3	---	---
Potassium	ppm	<1	4	---	---



MÉTAUX D'USURE

Fer	ppm	78	105	---	---
Cuivre	ppm	29	15	---	---
Plomb	ppm	1	<1	---	---
Étain	ppm	0	0	---	---
Aluminium	ppm	1	2	---	---
Chrome	ppm	<1	2	---	---
Molybdène	ppm	0	<1	---	---
Nickel	ppm	<1	<1	---	---
Titane	ppm	<1	3	---	---
Argent	ppm	<1	0	---	---
Manganèse	ppm	<1	2	---	---
Vanadium	ppm	0	0	---	---



ADDITIFS

Calcium	ppm	487	804	---	---
Magnésium	ppm	3	3	---	---
Zinc	ppm	908	1503	---	---
Phosphore	ppm	1021	750	---	---
Baryum	ppm	2	3	---	---
Bore	ppm	201	107	---	---

T:
F:

Diagnostic

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: JOSMER
Unique No: 5671054
Signed: Kevin Marson
Report Date: 03 Nov 2023



GRAPHS

