

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR LH50M 151293-1216 - Splitter Box

Sample No: LH0281562

Oil Type: NOT GIVEN



1625066 ONTARIO LTD.  
870 MACKAY RD  
PICKERING, ON  
CA L1W 2Y4  
Contact: Service Manager



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0281562	---	---	---
Date d'échant.	07 Dec 2023	---	---	---
Heures de la Machine	616	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	N/A	---	---	---
Statut de l'échant.	NORMAL	---	---	---



#### ÉTAT D'HUILE

Visc 40°C	cSt	45.4	---	---	---
-----------	-----	------	-----	-----	-----



#### CONTAMINATION

Eau	%	NEG	---	---	---
Silicium	ppm	3	---	---	---
Sodium	ppm	4	---	---	---
Potassium	ppm	2	---	---	---



#### MÉTAUX D'USURE

Fer	ppm	9	---	---	---
Cuivre	ppm	1	---	---	---
Plomb	ppm	<1	---	---	---
Étain	ppm	0	---	---	---
Aluminium	ppm	<1	---	---	---
Chrome	ppm	0	---	---	---
Molybdène	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	<1	---	---	---
Manganèse	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIFS

Calcium	ppm	1324	---	---	---
Magnésium	ppm	8	---	---	---
Zinc	ppm	714	---	---	---
Phosphore	ppm	608	---	---	---
Baryum	ppm	<1	---	---	---
Bore	ppm	1	---	---	---

T:  
F:

#### Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: 162PIC  
Unique No: 5695013  
Signed: Kevin Marson  
Report Date: 11 Dec 2023



### GRAPHS

