

LIEBHERR LR636 018134-1275 - Splitter Box

Sample No: LH0281607

Oil Type:

GEAR OIL SAE 75W90

INFORMATION SUR L'ÉCHANTILLON

0

LH0281607

18 Dec 2023 6558

Changed NORMAL

0 106

| Numéro d'échant. | |
|----------------------|--|
| Date d'échant. | |
| Heures de la Machine | |
| Heures de l'huile | |
| Huile changée | |
| Statut de l'echant. | |

ÉTAT D'HUILE

Visc 40°C

cSt

| CONTAMINATION | | | | | | | | |
|---------------|-----|-------------|--|--|--|--|--|--|
| Eau | % | NEG | | | | | | |
| Silicium | ppm | 2 | | | | | | |
| Sodium | ppm | 01 | | | | | | |
| Potassium | ppm | ○ <1 | | | | | | |

| Ä | | | | |
|-----------|----------|-------------|------|--|
| 🥸 MéT | 'AUX D'l | JSURE | | |
| Fer | 222 | 04 | | |
| - | ppm | • | | |
| Cuivre | ppm | ○ <1 | | |
| Plomb | ppm | ○ <1 | | |
| Étain | ppm | 0 | | |
| Aluminium | ppm | ○ <1 | | |
| Chrome | ppm | 0 🔘 | | |
| Molybdène | ppm | 0 | | |
| Nickel | ppm | 0 | | |
| Titane | ppm | 0 | | |
| Argent | ppm | <1 | | |
| Manganèse | ppm | 0 | | |
| Vanadium | ppm | 0 | | |

0 **ADDITIFS** Calcium 0 10 ppm Magnésium 01 ppm Zinc 011 ppm Phosphore ppm 0 1229 Baryum ○ <1 ppm Bore ppm 0 306





CON-DRAIN LTD. 30 FLORAL PARKWAY CONCORD, ON CA L4K 4R1 Contact: B BAXTER B.BAXTER@CONDRAIN.COM

T:

F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:CUnique No:56Signed:WReport Date:19

CON30CON 5697282 Wes Davis 19 Dec 2023

Submitted By: ?





GRAPHS

 \odot

