

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH22M 142190-1250 - Front Right Wheel Hub

Sample No: LH0285124

Oil Type: {unknown}



Combined Metals Industries
8470 Keele Street
Concord, ON
CA L4K 2S1
Contact: Service Manager

T:
F:



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0285124	LH0256996	---	---
Date d'échant.	29 Jan 2024	19 Mar 2023	---	---
Heures de la Machine	2242	754	---	---
Heures de l'huile	0	0	---	---
Huile changée	N/A	Not Changd	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	94.3	64.5	---	---
-----------	-----	------	------	-----	-----



CONTAMINATION

Eau	%	NEG	NEG	---	---
Silicium	ppm	2	9	---	---
Sodium	ppm	10	17	---	---
Potassium	ppm	<1	<1	---	---



MÉTAUX D'USURE

Fer	ppm	24	38	---	---
Cuivre	ppm	10	11	---	---
Plomb	ppm	<1	<1	---	---
Étain	ppm	0	<1	---	---
Aluminium	ppm	<1	1	---	---
Chrome	ppm	0	1	---	---
Molybdène	ppm	0	<1	---	---
Nickel	ppm	<1	0	---	---
Titane	ppm	0	<1	---	---
Argent	ppm	0	0	---	---
Manganèse	ppm	<1	2	---	---
Vanadium	ppm	0	0	---	---



ADDITIFS

Calcium	ppm	750	3633	---	---
Magnésium	ppm	4	11	---	---
Zinc	ppm	331	1401	---	---
Phosphore	ppm	1178	1222	---	---
Baryum	ppm	<1	<1	---	---
Bore	ppm	210	98	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: COM847CON
Unique No: 5721322
Signed: Wes Davis
Report Date: 30 Jan 2024



GRAPHS

