

LIEBHERR LH40M 146402-1215 - Front Left Wheel Hub

Sample No: LH0285157

Oil Type: **GEAR OIL SAE 80W90**

ÉTAT D'HUILE

Calcium

Zinc

Bore

Magnésium

Phosphore

Baryum

INFORMATION SUR L'ÉCHANTILLON				
Numéro d'échant.	LH0285157			
Date d'échant.	08 Feb 2024			
Heures de la Machine	0			
Heures de l'huile	0			
Huile changée	N/A			
Statut de l'echant.	NORMAL			



JOSEPH & COMPANY INC 257 VICTORIA ST N KITCHENER, ON CA N2H 5C9 Contact: Service Manager

Т	:
F	:

Diagnostic

Visc 40°C	cSt	154	 	
- 1 min				
CONT	TAMINA	TION		
Eau	%	NEG	 	
Silicium	ppm	10	 	
Sodium	ppm	6	 	
Potassium	ppm	2	 	

(O) MÁI				
Mé1	I'AUX D'U	JSURE		
Fer	ppm	0 77	 	
Cuivre	ppm	19	 	
Plomb	ppm	2	 	
Étain	ppm	0	 	
Aluminium	ppm	2	 	
Chrome	ppm	O <1	 	
Molybdène	ppm	2	 	
Nickel	ppm	0	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	3	 	
Vanadium	ppm	0	 	

sp
ind
GI
CO
ΑI
Th
СО
СО
the
••••

to monitor. The fluid was not pecified, however, a fluid match dicates that this fluid is (GENERIC) EAR OIL SAE 80W90. Please onfirm. Il component wear rates are normal.

Resample at the next service interval

here is no indication of any ontamination in the oil. The ondition of the oil is acceptable for e time in service.

Depot:	JOS257KIT
Unique No:	5723911
Signed:	Wes Davis
Report Date:	13 Feb 2024

135

2

44

<1</p>

3

1379

mqq

ppm

ppm

ppm

ppm

ppm

LIEBHERR







GRAPHS

