

LIEBHERR

CONSTRUCTION EQUIPMENT



[(374940)] LIEBHERR LH30M 137944-1253 - Front Left Wheel

Sample No: LH0278720

Oil Type: {unknown}



KINGS AUTO WRECKERS
1866 DRUMMOND LINE
PETERBOROUGH, ON
CA K9J 6X8
Contact: Service Manager

T:
F:



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0278720	LH0239297	---	---
Date d'échant.	22 Feb 2024	31 Aug 2022	---	---
Heures de la Machine	2777	551	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	104	64.5	---	---
-----------	-----	-----	------	-----	-----



CONTAMINATION

Eau	%	NEG	NEG	---	---
Silicium	ppm	4	6	---	---
Sodium	ppm	8	17	---	---
Potassium	ppm	1	1	---	---



MÉTAUX D'USURE

Fer	ppm	21	13	---	---
Cuivre	ppm	18	18	---	---
Plomb	ppm	<1	<1	---	---
Étain	ppm	0	0	---	---
Aluminium	ppm	<1	1	---	---
Chrome	ppm	<1	<1	---	---
Molybdène	ppm	0	0	---	---
Nickel	ppm	0	0	---	---
Titane	ppm	0	<1	---	---
Argent	ppm	0	0	---	---
Manganèse	ppm	<1	<1	---	---
Vanadium	ppm	0	0	---	---



ADDITIFS

Calcium	ppm	845	3475	---	---
Magnésium	ppm	4	10	---	---
Zinc	ppm	341	1337	---	---
Phosphore	ppm	1526	1173	---	---
Baryum	ppm	0	0	---	---
Bore	ppm	147	96	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINPET
Unique No: 5734831
Signed: Kevin Marson
Report Date: 26 Feb 2024



GRAPHS

