

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### [(374940)] LIEBHERR LH30M 137944-1253 - Rear Left Wheel

Sample No: LH0278723

Oil Type: {unknown}



**KINGS AUTO WRECKERS**  
1866 DRUMMOND LINE  
PETERBOROUGH, ON  
CA K9J 6X8  
Contact: Service Manager

T:  
F:



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0278723	LH0239298	---	---
Date d'échant.	22 Feb 2024	31 Aug 2022	---	---
Heures de la Machine	2777	551	---	---
Heures de l'huile	0	0	---	---
Huile changée	Changed	Changed	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



#### ÉTAT D'HUILE

Visc 40°C	cSt	95.2	74.3	---	---
-----------	-----	------	------	-----	-----



#### CONTAMINATION

Eau	%	NEG	NEG	---	---
Silicium	ppm	2	6	---	---
Sodium	ppm	3	10	---	---
Potassium	ppm	<1	1	---	---



#### MÉTAUX D'USURE

Fer	ppm	6	5	---	---
Cuivre	ppm	7	3	---	---
Plomb	ppm	0	0	---	---
Étain	ppm	0	0	---	---
Aluminium	ppm	<1	<1	---	---
Chrome	ppm	0	0	---	---
Molybdène	ppm	0	0	---	---
Nickel	ppm	<1	0	---	---
Titane	ppm	0	0	---	---
Argent	ppm	0	0	---	---
Manganèse	ppm	0	2	---	---
Vanadium	ppm	0	0	---	---



#### ADDITIFS

Calcium	ppm	414	2370	---	---
Magnésium	ppm	4	8	---	---
Zinc	ppm	176	936	---	---
Phosphore	ppm	1250	1200	---	---
Baryum	ppm	<1	0	---	---
Bore	ppm	255	160	---	---

#### Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KINPET  
Unique No: 5734838  
Signed: Wes Davis  
Report Date: 23 Feb 2024



### GRAPHS

