



[fondation beliveau] LIEBHERR LH40M 098208 - Transmissio

Sample No: LH

Oil Type: {unknown}



LIEBHERR CANADA LTEE
444 AVENUE DE LA FRICHE
DOLBEAU-MISTASSINI, QC
CA G8L 3M7
Contact: Martin Gagnon
martin.gagnon@liebherr.com
T:
F: (418)276-9844



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH	LH	---	---
Date d'échant.	04 Mar 2024	29 Jun 2023	---	---
Heures de la Machine	6970	6242	---	---
Heures de l'huile	0	135	---	---
Huile changée	Not Changd	Not Changd	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	66.6	71.6	---	---
-----------	-----	------	------	-----	-----



CONTAMINATION

Eau	%	NEG	NEG	---	---
Silicium	ppm	5	5	---	---
Sodium	ppm	14	13	---	---
Potassium	ppm	2	2	---	---



MÉTAUX D'USURE

Fer	ppm	40	17	---	---
Cuivre	ppm	56	27	---	---
Plomb	ppm	2	1	---	---
Étain	ppm	3	1	---	---
Aluminium	ppm	8	5	---	---
Chrome	ppm	<1	<1	---	---
Molybdène	ppm	0	0	---	---
Nickel	ppm	<1	0	---	---
Titane	ppm	0	0	---	---
Argent	ppm	0	0	---	---
Manganèse	ppm	28	11	---	---
Vanadium	ppm	0	0	---	---



ADDITIFS

Calcium	ppm	4260	4220	---	---
Magnésium	ppm	22	22	---	---
Zinc	ppm	1183	1177	---	---
Phosphore	ppm	1120	1134	---	---
Baryum	ppm	<1	<1	---	---
Bore	ppm	181	180	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: LBADOL
Unique No: 5737116
Signed: Kevin Marson
Report Date: 06 Mar 2024



GRAPHS

