

GEAR OIL SAE 75W90

## [(357696)] LIEBHERR LH50M 133969-1216 - Rear Right Whee


Sample No: LH0286529

Oil Type:

Statut de l'echant.

<b>.</b>								
	J INFORMATION SUR L'ÉCHANTILLON							
Numéro d'échant.	LH0286529	LH0230830						
Date d'échant.	04 Mar 2024	19 Aug 2022						
Heures de la Machine	3503	1605						
Heures de l'huile	0	0						
Huile changée	Changed	Changed						

NORMAL



NORMAL

Eau	%	NEG	NEG			
Silicium	ppm	0 14	03			
Sodium	ppm	07	0 1			
Potassium	maa	0 2	○ <1			

<b>A</b>				
Mé	raux d'l	JSURE		
Fer	ppm	0 89	0 14	 
Cuivre	ppm	52	0 6	 
Plomb	ppm	2	0	 
Étain	ppm	0	0	 
Aluminium	ppm	03	◯ <1	 
Chrome	ppm	<b>○</b> <1	0	 
Molybdène	ppm	0 2	0	 
Nickel	ppm	○ <1	0	 
Titane	ppm	0	0	 
Argent	ppm	0	0	 
Manganèse	ppm	04	<1	 
Vanadium	ppm	0	0	 

٥ **ADDITIFS** Calcium 0 135 ppm 54 Magnésium 03 ppm 63 Zinc 0 89 ppm Phosphore ppm 0 1241 1153 Baryum 0 ppm 0 Bore ppm 0 167 285





## PRIESTLY DEMOLITION

3200 LLOYDTOWN AURORA RD KING, ON CA LOG 1J0 Contact: Krystal Breedeon kbreedon@priestly.ca T: F:

## Diagnostic

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.An increase in the copper level is noted. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:FUnique No:5Signed:KReport Date:0


PRIKIN 5737762 Kevin Marson 07 Mar 2024





GRAPHS

 $\odot$ 



ID du rapport: PRIKIN [WCAMIS] 02620652 (Generated: 03/11/2024 09:15:03) Rev: 1