

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 1537 69-1253 - Rear Differential

Sample No: LH0278092

Oil Type: {unknown}



9262-1408 Quebec Inc.
13125 Rue Industrielle
Sorel-Tracy, QC
CA J3R 0E8
Contact: Service Manager



INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0278092	---	---	---
Date d'échant.	10 Mar 2024	---	---	---
Heures de la Machine	2000	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	N/A	---	---	---
Statut de l'échant.	NORMAL	---	---	---



ÉTAT D'HUILE

Visc 40°C	cSt	77.0	---	---	---
-----------	-----	------	-----	-----	-----



CONTAMINATION

Eau	%	NEG	---	---	---
Silicium	ppm	7	---	---	---
Sodium	ppm	2	---	---	---
Potassium	ppm	<1	---	---	---



MÉTAUX D'USURE

Fer	ppm	2	---	---	---
Cuivre	ppm	<1	---	---	---
Plomb	ppm	0	---	---	---
Étain	ppm	0	---	---	---
Aluminium	ppm	1	---	---	---
Chrome	ppm	0	---	---	---
Molybdène	ppm	38	---	---	---
Nickel	ppm	<1	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIFS

Calcium	ppm	1653	---	---	---
Magnésium	ppm	474	---	---	---
Zinc	ppm	1012	---	---	---
Phosphore	ppm	910	---	---	---
Baryum	ppm	0	---	---	---
Bore	ppm	64	---	---	---

T:
F:

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: 926SOR
Unique No: 5746300
Signed: Kevin Marson
Report Date: 12 Mar 2024



GRAPHS

