

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR LH30M 1537 69-1253 - Front Differential

Sample No: LH0278091

Oil Type: {unknown}



9262-1408 Quebec Inc.  
13125 Rue Industrielle  
Sorel-Tracy, QC  
CA J3R 0E8  
Contact: Service Manager



#### INFORMATION SUR L'ÉCHANTILLON

Numéro d'échant.	LH0278091	---	---	---
Date d'échant.	10 Mar 2024	---	---	---
Heures de la Machine	2000	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	N/A	---	---	---
Statut de l'échant.	NORMAL	---	---	---



#### ÉTAT D'HUILE

Visc 40°C	cSt	76.2	---	---	---
-----------	-----	------	-----	-----	-----

T:  
F:



#### CONTAMINATION

Eau	%	NEG	---	---	---
Silicium	ppm	10	---	---	---
Sodium	ppm	2	---	---	---
Potassium	ppm	<1	---	---	---

#### Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The condition of the oil is acceptable for the time in service.



#### MÉTAUX D'USURE

Fer	ppm	2	---	---	---
Cuivre	ppm	<1	---	---	---
Plomb	ppm	0	---	---	---
Étain	ppm	0	---	---	---
Aluminium	ppm	1	---	---	---
Chrome	ppm	0	---	---	---
Molybdène	ppm	36	---	---	---
Nickel	ppm	<1	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIFS

Calcium	ppm	1595	---	---	---
Magnésium	ppm	463	---	---	---
Zinc	ppm	977	---	---	---
Phosphore	ppm	870	---	---	---
Baryum	ppm	0	---	---	---
Bore	ppm	61	---	---	---

Depot: 926SOR  
Unique No: 5746356  
Signed: Kevin Marson  
Report Date: 11 Mar 2024



### GRAPHS

