CONSTRUCTION EQUIPMENT



Sample No: LH0284245

Oil Type: **TDH FLUID SAE 75W80**

INFORMATION SUR L'ÉCHANTILLON					
Numéro d'échant.	LH0284245				
Date d'échant.	06 Mar 2024				
Heures de la Machine	2334				
Heures de l'huile	0				
Huile changée	N/A				
Statut de l'echant.	NORMAL				



**						
CONTAMINATION						
Eau	%	NEG				
Silicium	ppm	8				
Sodium	ppm	3				
Potassium	ppm	2				
(Ö)						

MéT.	AUX D'U	SURE		
Fer	ppm	5	 	
Cuivre	ppm	() <1	 	
Plomb	ppm	() <1	 	
Étain	ppm	0	 	
Aluminium	ppm	1	 	
Chrome	ppm	0	 	
Molybdène	ppm	0	 	
Nickel	ppm	() <1	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	0	 	
Vanadium	ppm	0	 	

variaululli	ppiii	U				
ADDITIES						
ADDITIFS						
Calcium	ppm	3402				
Magnésium	ppm	16				
Zinc	ppm	1337				
Phosphore	ppm	1133				
Baryum	ppm	0				
Bore	ppm	94				



Fraser Pacific Enterprises 3883 Sumas Mountain road Abbotsford, BC CA V3G 2K6

Contact: Service Manager

T: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDH FLUID SAE 75W80. Please confirm.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: FRA388ABB **Unique No:** 5747195 Signed: Kevin Marson **Report Date:** 15 Mar 2024

LIEBHERR







GRAPHS

