BHERR **CONSTRUCTION EQUIPMENT**

LIEBHERR LH50M 146771-1216 - Diesel Engine

PETRO CANADA DURON UHP 5W30

0 11.7

101

Sample No: LH0287049

Oil Type:

Information sur l'échantillon

Numéro d'échant.	LH0287049	 	
Date d'échant.	15 Apr 2024	 	
Heures de la Machine	1892	 	
Heures de l'huile	0	 	
Huile changée	Changed	 	
Statut de l'echant.	NORMAL	 	

État d'huile Visc 100°C

Oxydation (PA) يقوم

Contamination								
Eau	%	NEG						
% de suie	%	0						
Nitration (PA)	%	94						
Sulfatation (PA)	%	67						
Glycol	%	NEG						
Essence	%	0.3						
Silicium	ppm	6						
Sodium	ppm	5						
Potassium	ppm	○ <1						

Métaux d'usure

cSt

%

Fer	ppm	8 🔘	 	
Cuivre	ppm	36	 	
Plomb	ppm	○ <1	 	
Étain	ppm	0 ()	 	
Aluminium	ppm	01	 	
Chrome	ppm	○ <1	 	
Molybdène	ppm	60	 	
Nickel	ppm	0 🔘	 	
Titane	ppm	0	 	
Argent	ppm	0 ()	 	
Manganèse	ppm	○ <1	 	
Vanadium	ppm	0	 	

¢ **Additifs** Calcium ppm 927 Magnésium ppm 0 1121 Zinc 0 1170 ppm Phosphore 0 928 ppm Baryum ppm 04 Bore ppm 0 39





Recyclage de Metaux Integre Inc. - RMI Inc. 1000 Route 389 Fermont, QC CA GOG 1J0 Contact: Paul Germain pgermain@rmi-imr.com т: F:

Diagnostic

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: RECFER Unique No: 5774557 Signed: Kevin Marson **Report Date:** 07 May 2024


Submitted By: Bruno Savard





٢

Graphs



ID du rapport: RECFER [WCAMIS] 02633404 (Generated: 05/08/2024 07:30:32) Rev: 1

Submitted By: Bruno Savard Page 2 sur 2