

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L566 071885-1758 - Front Differential

Sample No: LH0291254

Oil Type: {unknown}



Information sur l'échantillon

Numéro d'échant.	LH0291254	LH0276135	LH0261543	---
Date d'échant.	06 May 2024	12 Oct 2023	11 Jun 2023	---
Heures de la Machine	1939	937	500	---
Heures de l'huile	0	0	0	---
Huile changée	Changed	N/A	Changed	---
Statut de l'échant.	NORMAL	NORMAL	ABNORMAL	---

MONAGHAN MUSHROOMS LTD
 7345 GUELPH LINE
 CAMPBELLVILLE, ON
 CA L0P 1B0
 Contact: Steven Cargill
 s.cargill@monaghan-mushrooms.com
 T:
 F:



État d'huile

Visc 40°C	cSt	96.3	108	194	---
-----------	-----	------	-----	-----	-----



Contamination

Eau	%	NEG	NEG	NEG	---
Silicium	ppm	8	15	24	---
Sodium	ppm	3	4	6	---
Potassium	ppm	<1	<1	<1	---



Métaux d'usure

Fer	ppm	307	391	376	---
Cuivre	ppm	119	186	307	---
Plomb	ppm	3	5	10	---
Étain	ppm	6	9	16	---
Aluminium	ppm	<1	1	2	---
Chrome	ppm	1	2	2	---
Molybdène	ppm	0	0	0	---
Nickel	ppm	2	3	5	---
Titane	ppm	0	0	0	---
Argent	ppm	1	<1	0	---
Manganèse	ppm	9	17	33	---
Vanadium	ppm	0	0	0	---



Additifs

Calcium	ppm	14	12	6	---
Magnésium	ppm	2	2	3	---
Zinc	ppm	32	47	54	---
Phosphore	ppm	2760	3031	2489	---
Baryum	ppm	1	<1	0	---
Bore	ppm	255	212	3	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: MONCAM
 Unique No: 5775076
 Signed: Kevin Marson
 Report Date: 07 May 2024



Graphs

