

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR LH50M 077508 - Transmission

Sample No: LH0289766

Oil Type: {unknown}



**J.M. BASTILLE ACIER INC**  
396 RUE TEMISCOUATA,, CP 744  
RIVIERE DU LOUP, QC  
CA G5R 3Z3  
Contact: MANAGER SERVICE

T: (418)862-3346  
F:



#### Information sur l'échantillon

Numéro d'échant.	LH0289766	---	---	---
Date d'échant.	01 May 2024	---	---	---
Heures de la Machine	16364	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	N/A	---	---	---
Statut de l'échant.	NORMAL	---	---	---



#### État d'huile

Visc 40°C	cSt	53.0	---	---	---
-----------	-----	------	-----	-----	-----



#### Contamination

Eau	%	NEG	---	---	---
Silicium	ppm	2	---	---	---
Sodium	ppm	4	---	---	---
Potassium	ppm	3	---	---	---



#### Métaux d'usure

Fer	ppm	14	---	---	---
Cuivre	ppm	3	---	---	---
Plomb	ppm	0	---	---	---
Étain	ppm	0	---	---	---
Aluminium	ppm	2	---	---	---
Chrome	ppm	0	---	---	---
Molybdène	ppm	46	---	---	---
Nickel	ppm	0	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	0	---	---	---
Manganèse	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



#### Additifs

Calcium	ppm	1259	---	---	---
Magnésium	ppm	819	---	---	---
Zinc	ppm	1207	---	---	---
Phosphore	ppm	1086	---	---	---
Baryum	ppm	0	---	---	---
Bore	ppm	105	---	---	---

#### Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: JMBRIV  
Unique No: 5776149  
Signed: Kevin Marson  
Report Date: 13 May 2024



### Graphs

