

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### [(353859)] LIEBHERR LH50M 132600-1216 - Transmission (Mc

Sample No: LH

Oil Type: TDTO FLUID SAE 10W



#### Information sur l'échantillon

Numéro d'échant.	LH	LH0209351	---	---
Date d'échant.	19 Apr 2024	20 Jan 2022	---	---
Heures de la Machine	14280	0	---	---
Heures de l'huile	0	0	---	---
Huile changée	N/A	N/A	---	---
Statut de l'échant.	NORMAL	NORMAL	---	---

HUBERT & FILS

474 ROUTE 105  
BOIS-FRANC, QC  
CA J9E 3A9

Contact: Eric Brisebois  
ericbrisebois99@gmail.com

T:  
F:



#### État d'huile

Visc 40°C	cSt	42.9	49.4	---	---
-----------	-----	------	------	-----	-----



#### Contamination

Eau	%	NEG	NEG	---	---
Silicium	ppm	12	4	---	---
Sodium	ppm	2	21	---	---
Potassium	ppm	7	3	---	---



#### Métaux d'usure

Fer	ppm	30	39	---	---
Cuivre	ppm	18	60	---	---
Plomb	ppm	0	2	---	---
Étain	ppm	<1	2	---	---
Aluminium	ppm	1	3	---	---
Chrome	ppm	0	<1	---	---
Molybdène	ppm	0	27	---	---
Nickel	ppm	0	<1	---	---
Titane	ppm	<1	0	---	---
Argent	ppm	0	0	---	---
Manganèse	ppm	2	27	---	---
Vanadium	ppm	0	<1	---	---



#### Additifs

Calcium	ppm	2225	2219	---	---
Magnésium	ppm	21	446	---	---
Zinc	ppm	1160	1140	---	---
Phosphore	ppm	1088	1143	---	---
Baryum	ppm	0	<1	---	---
Bore	ppm	62	4	---	---

#### Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDTO FLUID SAE 10W. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: HUBBOI  
Unique No: 5787696  
Signed: Wes Davis  
Report Date: 30 May 2024



### Graphs

