# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

# LIEBHERR LH22M 137772-1525 - Rear Differential

Sample No: LH0232635
Oil Type: SAE 75W90



Statut de l'echant.		NURWAL					
État d'hvile							
Visc 40°C	cSt	63.1					
-1							

Contamination							
Eau	%	NEG					
Silicium	ppm	<b>4</b>					
Sodium	ppm	<b>17</b>					
Potassium	ppm	<b>0</b> <1					

<b>W</b> ét	aux d'us	ure		
Fer	ppm	<b>27</b>	 	
Cuivre	ppm	<b>14</b>	 	
Plomb	ppm	<b>0</b>	 	
Étain	ppm	<b>0</b>	 	
Aluminium	ppm	<b>○</b> <1	 	
Chrome	ppm	<b>0</b> <1	 	
Molybdène	ppm	<b>0</b>	 	
Nickel	ppm	<b>0</b>	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	<b>2</b>	 	
Vanadium	ppm	0	 	

Additifs						
Calcium	ppm	3375				
Magnésium	ppm	<b>0</b> 10				
Zinc	ppm	1327				
Phosphore	ppm	<b>1105</b>				
Baryum	ppm	<b>3</b>				
Bore	ppm	<b>106</b>				



### **Excavation Dolbeau Inc.**

493 - 2ieme Avenue Dolbeau-Mistassini, QC CA G8L 1V3

Contact: Service Manager

T: F:

### Diagnostic

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:EXCDOLUnique No:5788621Signed:Wes DavisReport Date:03 Jun 2024





## **Graphs**

