

## LIEBHERR TA230 139463-1513 - Transmission (Auto)

Sample No: LH0285930

**Oil Type: DEXRON III** 

## Information sur l'échantillon LH0285930 Numéro d'échant. Date d'échant. 28 May 2024 Heures de la Machine 2360 Heures de l'huile 0 Huile changée Changed Statut de l'echant. NORMAL

État d'huile

Visc 40°C يليم ا

...

	_
	- 0+
	CSI

Conta	mination			
Eau	%	NEG	 	
Silicium	ppm	04	 	
Sodium	ppm	<b>3</b>	 	
Potassium	ppm	01	 	

34.8

Ä				
Ø Mét	taux d'us	ure		
Fer	ppm	64	 	
Cuivre	ppm	09	 	
Plomb	ppm	0	 	
Étain	ppm	0	 	
Aluminium	ppm	01	 	
Chrome	ppm	0	 	
Molybdène	ppm	0	 	
Nickel	ppm	0	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	<b>○</b> <1	 	
Vanadium	ppm	0	 	

٥ **Additifs** Calcium 0 151 ppm 04 Magnésium ppm Zinc 013 ppm Phosphore ppm 0 267 Baryum 2 ppm Bore ppm 0 115





LES ENTREPRISES LOU-VIL INC 255 BOUL. LOUIS XIV QUEBEC, QC CA G2K 1W6 Contact: Service Manager

T: (418)622-2958 F:

## Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: Unique No: Signed: **Report Date:** 

LOUQUE 5789976 Kevin Marson 10 Jun 2024 Submitted By: ?

## CONSTRUCTION EQUIPMENT



 $\bigcirc$ 

Graphs

