



LIEBHERR R926LC 054886-1715 - Splitter Box

Sample No: LH0291019

Oil Type:

GEAR OIL SAE 80W90

-										
Information sur l'échantillon										
Numéro d'échant.	LH0291019									
Date d'échant.	10 Jun 2024									
Heures de la Machine	899									
Heures de l'huile	0									
Huile changée	N/A									
Statut de l'echant.	NORMAL									

État d'huile

cSt

Visc 40°C	cSt	194	 	
111				
Con	taminati	on		
Eau	%	NEG	 	
Silicium	ppm	○ <1	 	
Sodium	ppm	3	 	
Potassium	ppm	○ <1	 	

\bigcirc Métaux d'usure Fer ppm 0 32 Cuivre ppm ○ <1 Plomb 0 ppm Étain ppm 0 Aluminium ppm 0 <1 Chrome ppm 0 Molybdène 0 (ppm Nickel ppm 0 Titane ppm 0 Argent 0 ppm Manganèse ppm Vanadium ppm 0

0 **Additifs** Calcium 0 11 ppm Magnésium ppm 02 Zinc 0 14 ppm Phosphore ppm 0 1516 Baryum ◯ <1 ppm Bore ppm 02



BDT EQUIPMENT CORPORATION

835 SAWMILL RD BLOOMINGDALE, ON CA NOB 1K0 Contact: Service Manager

т: F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.


All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: BDTBLO Unique No: 5798739 Signed: **Report Date:**

CONSTRUCTION EQUIPMENT



Ø



ID du rapport: BDTBLO [WCAMIS] 02641200 (Generated: 06/14/2024 12:29:47) Rev: 1