

LIEBHERR L550 076577-1825 - Splitter Box

0 178

Sample No: LH0290655

Oil Type:

Infor	mation	s cur l'	ócha	ntil

GEAR OIL SAE 80W90

Information sur l echantilion							
Numéro d'éch	ant.	LH0290655					
Date d'échant	•	11 Jun 2024					
Heures de la Ma	chine	541					
Heures de l'hi	ile	0					
Huile changée)	N/A					
Statut de l'ech	ant.	NORMAL					

Visc 40°C

État d'huile cSt

Contamination						
Eau	%	NEG				
Silicium	ppm	01				
Sodium	ppm	04				
Potassium	ppm	04				

 \bigcirc Métaux d'usure Fer ppm 0 86 Cuivre 02 ppm Plomb 0 ppm Étain ppm 0 Aluminium ppm 03 Chrome ppm 0 <1 Molybdène 08 ppm Nickel ppm 19 Titane ppm 0 Argent 0 ppm Manganèse 3 ppm Vanadium ppm 0

0 **Additifs** 0 16 Calcium ppm Magnésium 0 13 ppm Zinc 0 28 ppm Phosphore ppm 0 2198 Baryum 0 12 ppm Bore ppm 01





142975 CANADA LTEE (MIRONOR) 751 CH DE LA 2E CONCESSION

BROWNSBURG-CHATHAM, QC CA J8G 1S9 Contact: Francis Sylvestre

T: (450)898-9225 F:

Diagnostic

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: 142BRO Unique No: 5799614 Kevin Marson Signed: **Report Date:** 17 Jun 2024 Submitted By: Eric Leblond

CONSTRUCTION EQUIPMENT



 \odot

