

LIEBHERR L550 076577-1825 - Rear Differential

Sample No: LH0290653

Oil Type:

GEAR OIL SAE 80W90

0 195

Information sur l'échantillon									
LH0290653									
11 Jun 2024									
541									
0									
N/A									
NORMAL									
	LH0290653 11 Jun 2024 541 0 N/A	LH0290653 11 Jun 2024 541 0 N/A	LH0290653 11 Jun 2024 541 0 N/A						

État d'huile

Visc 40°C

.....

cSt

Conta	mination			
Eau	%	NEG	 	
Silicium	ppm	0 31	 	
Sodium	ppm	07	 	
Potassium	ppm	○ <1	 	

Métaux d'usure							
Fer	ppm	295					
Cuivre	ppm	91					
Plomb	ppm	02					
Étain	ppm	07					
Aluminium	ppm	02					
Chrome	ppm	02					
Molybdène	ppm	0					
Nickel	ppm	04					
Titane	ppm	0					
Argent	ppm	0					
Manganèse	ppm	21					
Vanadium	ppm	0					

٥ **Additifs** Calcium ppm 6 Magnésium ppm 03 Zinc 0 25 ppm Phosphore ppm 0 2208 Baryum ○ <1 ppm Bore ppm 02





142975 CANADA LTEE (MIRONOR) 751 CH DE LA 2E CONCESSION

BROWNSBURG-CHATHAM, QC CA J8G 1S9 Contact: Francis Sylvestre

T: (450)898-9225 F:

Diagnostic


Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: 142BRO Unique No: 5799621 Signed: Kevin Marson **Report Date:** 17 Jun 2024 Submitted By: Eric Leblond





٥



ID du rapport: 142BRO [WCAMIS] 02642082 (Generated: 06/17/2024 15:10:45) Rev: 1