

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L586 055418-1334 - Front Left Wheel Hub

Sample No: LH0296740

Oil Type: {unknown}



Information sur l'échantillon

Numéro d'échant.	LH0296740	---	---	---
Date d'échant.	07 Jul 2024	---	---	---
Heures de la Machine	15057	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Changed	---	---	---
Statut de l'échant.	NORMAL	---	---	---

CGC INC
 55 THIRD LINE RD
 HAGERSVILLE, ON
 CA N0A 1H0
 Contact: Mike Otterman
 motterman@cgcinc.com
 T: (905)768-2038
 F:



État d'huile

Visc 40°C	cSt	● 98.2	---	---	---
-----------	-----	--------	-----	-----	-----



Contamination

Eau	%	NEG	---	---	---
Silicium	ppm	● 2	---	---	---
Sodium	ppm	● <1	---	---	---
Potassium	ppm	● <1	---	---	---

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



Métaux d'usure

Fer	ppm	● 108	---	---	---
Cuivre	ppm	● 11	---	---	---
Plomb	ppm	● 0	---	---	---
Étain	ppm	● <1	---	---	---
Aluminium	ppm	● <1	---	---	---
Chrome	ppm	● <1	---	---	---
Molybdène	ppm	0	---	---	---
Nickel	ppm	● 0	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	<1	---	---	---
Manganèse	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



Additifs

Calcium	ppm	18	---	---	---
Magnésium	ppm	2	---	---	---
Zinc	ppm	12	---	---	---
Phosphore	ppm	2502	---	---	---
Baryum	ppm	0	---	---	---
Bore	ppm	295	---	---	---

Depot: CGCHAG
Unique No: 5811952
Signed: Wes Davis
Report Date: 09 Jul 2024



Graphs

