## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR L586 055418-1334 - Rear Right Wheel Hub

Sample No: LH0296737
Oil Type: {unknown}

Vanadium

Calcium

Zinc

Bore

Magnésium

Phosphore

Baryum

ppm

mqq

ppm

ppm

ppm

ppm

ppm

**Additifs** 

Infor	mation	sur l'échantillo	n	
Numéro d'échant.		LH0296737		 
Date d'échant.		07 Jul 2024		 
Heures de la Machine		15057		 
Heures de l'huile		0		 
Huile changée		Changed		 
Statut de l'echant.		NORMAL		 
État d	l'huile			
Visc 40°C	cSt	98.2		 
-1		0 11		
Combo	minati			
Eau	%	NEG		 
Silicium	ppm	<b>1</b>		 
Sodium	ppm	<b>0</b> 1		 
Potassium	ppm	<b>○</b> <1		 
(Ö)				
Méta	ux d'us	ure		
Fer	ppm	<b>2</b> 4		 
Cuivre	ppm	07		 
Plomb	ppm	0		 
Étain	ppm	O <1		 
Aluminium	ppm	0<1		 
Chrome	ppm	<b>○</b> <1		 
Molybdène	ppm	0		 
Nickel	ppm	<b>O</b> <1		 
Titane	ppm	0		 
Argent	ppm	0		 
Manganèse	ppm	<1		 



CGC INC
55 THIRD LINE RD
HAGERSVILLE, ON
CA N0A 1H0
Contact: Mike Otterman
motterman@cgcinc.com
T: (905)768-2038
F:

#### Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:CGCHAGUnique No:5811953Signed:Wes DavisReport Date:09 Jul 2024

15

2

16

0

291

2525

# LIEBHERR





#### **Graphs**

