

Sample Rating Trend

DEGRADATION




P 3 CROWN

Component Unknown Component

PETRO CANADA ENDURATEX EP 220 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the sample from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS

Sample Status		SEVERE						
Acid Number (AN)	mg KOH/g	ASTM D974*	0.40	6.73				
Appearance	scalar	Visual*	NORML	🔺 LAYRD				
Emulsified Water	scalar	Visual*		.2%				
Free Water	scalar	Visual*		<mark>▲</mark> >10%				
Visc @ 40°C	cSt	ASTM D7279(m)	220	<u> </u>				

Customer Id: VENSTC Sample No.: PC0061350 Lab Number: 02566286 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	We recommend that you drain the sample from the component if this has not already been done.			
Resample			?	We recommend an early resample to monitor this condition.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.			
Check Water Access			?	We advise that you check for the source of water entry.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

DEGRADATION

X

P 3 CROWN

Component Unknown Component

Fluid PETRO CANADA ENDURATEX EP 220 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the sample from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of water present in the sample. Excessive free water present.


Fluid Condition


The high AN level of the sample indicates the presence of oxi-polymerized products. The AN level is much higher than the recommended limit. Viscosity of sample indicates oil is within ISO 150 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The sample is no longer serviceable.


GAL)				Jun2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC0061350		
Sample Date		Client Info		22 Jun 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METAL	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)		16		
Chromium	ppm	ASTM D5185(m)		0		
Nickel	ppm	ASTM D5185(m)		<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)		<1		
Lead	ppm	ASTM D5185(m)		10		
Copper	ppm	ASTM D5185(m)		45		
Tin	ppm	ASTM D5185(m)		2		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	60	14		
Barium	ppm	ASTM D5185(m)	0	8		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)	0	<1		
Magnesium	ppm	ASTM D5185(m)	0	2		
Calcium	ppm	ASTM D5185(m)	0	9		
Phosphorus	ppm	ASTM D5185(m)	270	230		
Zinc	ppm	ASTM D5185(m)	0	64		
Sulfur	ppm	ASTM D5185(m)	11200	3566		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)		5		
Sodium	ppm	ASTM D5185(m)		2		
Potassium	ppm	ASTM D5185(m)	>20	1		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.40	6.73		



OIL ANALYSIS REPORT







: 5603332

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test Package : IND 2 (Additional Tests: KV100, TAN Man, VI)

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

Unique Number

Diagnostician : Kevin Marson

ISO 17025:2017 Accredited

Laboratory