


# **OIL ANALYSIS REPORT**



Machine Id 925009 Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)





## **DIAGNOSIS**

#### Recommendation

No corrective action is recommended at this time. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. The fluid was specified as PETRO CANADA DURON SHP 15W40, however, a fluid match indicates that this fluid is SAE 30 Diesel Engine Oil. Please confirm the oil type and grade on your next sample.

#### Wear

All component wear rates are normal.

#### Contamination

Light fuel dilution occurring. No other contaminants were detected in the oil.


### Fluid Condition

Viscosity of sample indicates oil is within SAE 30 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The condition of the oil is acceptable for the time in service.

N SHP 15W4U (	GAL)	May2020	Feb 2021 Aug 2021	Feb2022 Jun2022 Jan2023	Jul2023	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0078502	GFL0078522	GFL0071326
Sample Date		Client Info		11 Jul 2023	01 Apr 2023	11 Jan 2023
Machine Age	kms	Client Info		0	18287	17717
Oil Age	kms	Client Info		341880	0	552
Oil Changed		Client Info		N/A	Changed	Changed
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINA	TION	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	NEG
WEAR METAI	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>120	10	7	8
Chromium	ppm	ASTM D5185(m)	>20	<1	<1	<1
Nickel	ppm	ASTM D5185(m)	>5	6	8	5
Titanium	ppm	ASTM D5185(m)	>2	0	<1	<1
Silver	ppm	ASTM D5185(m)	>2	0	0	0
Aluminum	ppm	ASTM D5185(m)		2	1	2
Lead	ppm	ASTM D5185(m)	>40	1	<1	<1
Copper	ppm	ASTM D5185(m)	>330	1	1	1
Tin	ppm	ASTM D5185(m)	>15	<1	<1	<1
Antimony	ppm	ASTM D5185(m)	1.0	0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	28	4	2
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	60	43	58	58
Manganese	ppm	ASTM D5185(m)	0	<1	<1	<1
Magnesium	ppm	ASTM D5185(m)	1010	545	934	938
Calcium	ppm	ASTM D5185(m)	1070	1605	1106	1115
Phosphorus	ppm	ASTM D5185(m)	1150	781	1018	1018
Zinc	ppm	ASTM D5185(m)	1270	919	1151	1177
Sulfur	ppm	ASTM D5185(m)	2060	1948	2413	2386
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINAL	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	6	3	4
Sodium	ppm	ASTM D5185(m)		3	3	4
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	0
Fuel	%	ASTM D7593*	>3.0	2.2	<1.0	<1.0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>4	0.2	0	0.1
Nitration	Abs/cm	ASTM D7644*	>20	9.4	8.3	8.5
Sulfation	Abs/.1mm	ASTM D7024 ASTM D7415*	>30	22.7	22.1	20.9
				££.1		
						history2
FLUID DEGRA Oxidation	DATION		limit/base		history1	history2



# **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

: GFL0078502

: 02569652 : 5606698

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 246 - Windsor Received : 13 Jul 2023 Diagnosed

: 14 Jul 2023 Diagnostician : Kevin Marson **Test Package**: MOB 1 (Additional Tests: FuelDilution, PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

2700 Deziel Dr Windsor, ON CA N8W 5H8 Contact: Dave Varga dvarga@gflenv.com T: (519)944-8009