


OIL ANALYSIS REPORT

Sample Rating Trend





Machine Id **201001**

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (22 L

DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. No other corrective action is recommended at this time.

Wear

All component wear rates are normal.

Contamination

Light fuel dilution occurring. No other contaminants were detected in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.


₋ TR)		Jun2018	Nov2018 May2019	Nov2019 Sep2020 Jan2023	Jun2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0086498	GFL0068332	GFL0011361
Sample Date		Client Info		29 Jun 2023	03 Jan 2023	02 Sep 2020
Machine Age	hrs	Client Info		41580	3103	41580
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Changed	Changed	N/A
Sample Status				MARGINAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>80	7	7	22
Chromium	ppm	ASTM D5185(m)	>5	<1	<1	<1
Nickel	ppm	ASTM D5185(m)	>2	0	0	0
Titanium	ppm	ASTM D5185(m)		0	0	<1
Silver	ppm	ASTM D5185(m)	>3	<1	0	<1
Aluminum	ppm	ASTM D5185(m)	>30	2	2	2
Lead	ppm	ASTM D5185(m)	>30	0	0	10
Copper	ppm	ASTM D5185(m)	>150	2	2	317
Tin	ppm	ASTM D5185(m)	>5	0	0	<1
Antimony	ppm	ASTM D5185(m)		0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	23	13	2
Barium	ppm	ASTM D5185(m)	0	0	0	<1
Molybdenum	ppm	ASTM D5185(m)	60	58	53	59
Manganese	ppm	ASTM D5185(m)	0	<1	<1	<1
Magnesium	ppm	ASTM D5185(m)	1010	873	810	983
Calcium	ppm	ASTM D5185(m)	1070	1079	1263	1037
Phosphorus	ppm	ASTM D5185(m)	1150	1029	1057	1030
Zinc	ppm	ASTM D5185(m)	1270	1136	1139	1254
Sulfur	ppm	ASTM D5185(m)	2060	2572	2707	2435
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	3	3	4
Sodium	ppm	ASTM D5185(m)		4	4	5
Potassium	ppm	ASTM D5185(m)	>20	3	2	3
Fuel	%	ASTM D7593*	>5	<u>^</u> 2.9	<1.0	<1.0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0.1	0	0.4
Nitration	Abs/cm	ASTM D7624*	>20	6.9	7.3	9.7
Sulfation	Abs/.1mm	ASTM D7415*	>30	17.8	19.6	20.3
FLUID DEGRAI	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	13.4	14.3	16.9





OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML	NORML	
Emulsified Water	scalar	Visual*	>0.2	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.4	12.8	13.3	13.9






















CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: GFL0086498 : 02569665 : 5606711

Copper (ppm)

500

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 13 Jul 2023 Diagnosed

: 14 Jul 2023 Diagnostician : Wes Davis

Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel, Visual)

GFL Environmental - 217 - Aurora 14131 BAYVIEW AVE, AURORA YARD AURORA, ON

CA L4G 0K6 Contact: Mike Havens MHavens@gflenv.com T:

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (905)713-2445