

Area
SHARP BUS LINES
Machine Id
INTERNATIONAL 1336
Component
Diesel Engine
Fluid
PETRO CANADA DURON HP 15W40 (--- GAL)



DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

Iron ppm levels are abnormal. Cylinder, crank, or cam shaft wear is indicated.

Contamination

There is a moderate amount of fuel present in the oil. Light concentration of carbon/soot present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition

The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORMATION method limit/base current history1 history2

Sample Number	Client Info	PC0081284	---	---
Sample Date	Client Info	01 Sep 2023	---	---
Machine Age	kms	Client Info	212627	---
Oil Age	kms	Client Info	15622	---
Oil Changed	Client Info	Changed	---	---
Sample Status		ABNORMAL	---	---

CONTAMINATION method limit/base current history1 history2

Glycol	WC Method	NEG	---	---
--------	-----------	------------	-----	-----

WEAR METALS method limit/base current history1 history2

PQ	ASTM D8184*	0	---	---
Iron	ppm	ASTM D5185(m) >100	▲ 105	---
Chromium	ppm	ASTM D5185(m) >20	2	---
Nickel	ppm	ASTM D5185(m) >4	1	---
Titanium	ppm	ASTM D5185(m)	0	---
Silver	ppm	ASTM D5185(m) >3	0	---
Aluminum	ppm	ASTM D5185(m) >20	8	---
Lead	ppm	ASTM D5185(m) >40	1	---
Copper	ppm	ASTM D5185(m) >330	2	---
Tin	ppm	ASTM D5185(m) >15	0	---
Antimony	ppm	ASTM D5185(m)	0	---
Vanadium	ppm	ASTM D5185(m)	<1	---
Beryllium	ppm	ASTM D5185(m)	0	---
Cadmium	ppm	ASTM D5185(m)	0	---

ADDITIVES method limit/base current history1 history2

Boron	ppm	ASTM D5185(m) 0	2	---
Barium	ppm	ASTM D5185(m) 0	0	---
Molybdenum	ppm	ASTM D5185(m) 60	60	---
Manganese	ppm	ASTM D5185(m) 0	1	---
Magnesium	ppm	ASTM D5185(m) 1010	905	---
Calcium	ppm	ASTM D5185(m) 1070	956	---
Phosphorus	ppm	ASTM D5185(m) 1150	978	---
Zinc	ppm	ASTM D5185(m) 1270	1099	---
Sulfur	ppm	ASTM D5185(m) 2060	2314	---
Lithium	ppm	ASTM D5185(m)	<1	---


CONTAMINANTS method limit/base current history1 history2

Silicon	ppm	ASTM D5185(m) >25	6	---
Sodium	ppm	ASTM D5185(m)	3	---
Potassium	ppm	ASTM D5185(m) >20	2	---
Fuel	%	ASTM D7593* >2.0	▲ 3.9	---

INFRA-RED method limit/base current history1 history2

Soot %	%	ASTM D7844* >3	▲ 4.9	---
Nitration	Abs/cm	ASTM D7624* >20	15.5	---
Sulfation	Abs./1mm	ASTM D7415* >30	32.0	---


OIL ANALYSIS REPORT














FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs./1mm	ASTM D7414*	>25	22.6	---	---

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	NEG	---	---
Free Water	scalar	Visual*		NEG	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	118.2	121	---	---
Visc @ 100°C	cSt	ASTM D7279(m)	15.6	16.2	---	---
Viscosity Index (VI)	Scale	ASTM D2270*	139	143	---	---



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0081284 **Received** : 12 Sep 2023
Lab Number : 02581679 **Diagnosed** : 14 Sep 2023
Unique Number : 5642744 **Diagnostician** : Kevin Marson
Test Package : MOB 1 (Additional Tests: FuelDilution, KV40, PercentFuel, PQ, VI)

ICSB - Brantford
 567 Oak Park Rd.
 Brantford, ON
 CA N3T 5L8
 Contact: Doug Hall
 Djhall@sharpbus.com
 T: (519)751-3434
 F:

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.