

OIL ANALYSIS REPORT

Sam







Ford F350

Component **Diesel Engine**

SAE 10W30 (--- GAL)

DIAGNOSIS

Recommendation

The component was not specified so we have determined that this is a diesel engine based on the fluid type in use. Please specify the correct component type on your next sample. We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. We recommend that you drain the oil from the component if this has not already been done. We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of dirt present in the oil.

Fluid Condition

The oil is no longer serviceable due to the presence of contaminants.


				Oct2023		
SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0077012		
Sample Date		Client Info		04 Oct 2023		
Machine Age	kms	Client Info		203573		
Oil Age	kms	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	ON	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METALS	3	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	49		
Chromium	ppm	ASTM D5185(m)	>20	2		
Nickel	ppm	ASTM D5185(m)	>4	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>3	<1		
Aluminum	ppm	ASTM D5185(m)	>20	5		
Lead	ppm	ASTM D5185(m)	>40	<1		
Copper	ppm	ASTM D5185(m)	>330	3		
Tin	ppm	ASTM D5185(m)	>15	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		2		
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)		55		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		828		
Calcium	ppm	ASTM D5185(m)		909		
Phosphorus	ppm	ASTM D5185(m)		861		
Zinc	ppm	ASTM D5185(m)		1019		
Sulfur	ppm	ASTM D5185(m)		2237		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANT	ΓS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	40		
Sodium	ppm	ASTM D5185(m)	>228	3		
Potassium	ppm	ASTM D5185(m)	>20	0		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	1		
Nitration	Abs/cm	ASTM D7624*	>20	15.6		
Sulfation	Abs/.1mm	ASTM D7415*	>30	29.9		
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
Out detiens	A la a / d	ACTM D7414*	. 05	24.2		

Oxidation

34.3



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 575 - Squamish Hauling : GFL0077012

+02587496: 5656562

Received : 06 Oct 2023 Diagnosed : 06 Oct 2023

Diagnostician : Kevin Marson

Test Package : MOB 1 (Additional Tests: KV40, VI, Visual) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

38950 Queens Way, Squamish, BC CA V8B 0K8 Contact: Dean Imbeau dimbeau@gflenv.com

> T: (604)892-5604 F: (604)892-5238