

OIL ANALYSIS REPORT

SHARP BUS LINES Machine Id INTERNATIONAL 1366

Component

Diesel Engine

PETRO CANADA 15W40 (--- GAL)

Sample Rating Trend FUEL Aug/2023

DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition

Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

| | | | 1 | Aug2023 | | |
|--|--|--|---|--|-------------------|-------------------|
| SAMPLE INFORM | MATION | method | limit/base | current | history1 | history2 |
| Sample Number | | Client Info | | PC0081412 | | |
| Sample Date | | Client Info | | 09 Aug 2023 | | |
| Machine Age | hrs | Client Info | | 192329 | | |
| Oil Age | hrs | Client Info | | 1579 | | |
| Oil Changed | | Client Info | | Changed | | |
| Sample Status | | | | SEVERE | | |
| CONTAMINATI | ION | method | limit/base | current | history1 | history2 |
| Glycol | | WC Method | | NEG | | |
| WEAR METALS | S | method | limit/base | current | history1 | history2 |
| Iron | ppm | ASTM D5185(m) | >100 | 15 | | |
| Chromium | ppm | ASTM D5185(m) | >20 | 1 | | |
| Nickel | ppm | ASTM D5185(m) | >4 | <1 | | |
| Titanium | ppm | ASTM D5185(m) | | 0 | | |
| Silver | ppm | ASTM D5185(m) | >3 | <1 | | |
| Aluminum | ppm | ASTM D5185(m) | >20 | 5 | | |
| Lead | ppm | ASTM D5185(m) | >40 | <1 | | |
| Copper | ppm | ASTM D5185(m) | >330 | <1 | | |
| Tin | ppm | ASTM D5185(m) | >15 | 0 | | |
| Antimony | ppm | ASTM D5185(m) | | 0 | | |
| Vanadium | ppm | ASTM D5185(m) | | 0 | | |
| Beryllium | ppm | ASTM D5185(m) | | 0 | | |
| Cadmium | ppm | ASTM D5185(m) | | 0 | | |
| | | | | | | |
| ADDITIVES | | method | limit/base | current | history1 | history2 |
| ADDITIVES Boron | ppm | method ASTM D5185(m) | limit/base | current | history1 | history2 |
| | ppm | | limit/base | | · · | |
| Boron | | ASTM D5185(m) | limit/base | <1 | | |
| Boron Barium | ppm | ASTM D5185(m) ASTM D5185(m) | limit/base | <1 <1 | | |
| Boron Barium Molybdenum | ppm ppm | ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) | limit/base | <1 <1 48 | | |
| Boron Barium Molybdenum Manganese | ppm ppm | ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) | limit/base | <1 <1 48 0 | | |
| Boron Barium Molybdenum Manganese Magnesium | ppm ppm ppm | ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) | limit/base | <1 <1 48 0 747 | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium | ppm ppm ppm ppm | ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) | limit/base | <1 <1 48 0 747 806 | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus | ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base | <1 <1 48 0 747 806 819 | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc | ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base | <1 <1 48 0 747 806 819 941 | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur | ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base | <1 <1 48 0 747 806 819 941 2059 | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium | ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | | <1 <1 48 0 747 806 819 941 2059 <1 | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN | ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base | <1 <1 48 0 747 806 819 941 2059 <1 current | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon | ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) method ASTM D5185(m) | limit/base | <1 <1 48 0 747 806 819 941 2059 <1 current | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium | ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base >25 | <1 <1 48 0 747 806 819 941 2059 <1 current 3 | | history2 |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium | ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base >25 >20 | <1 <1 48 0 747 806 819 941 2059 <1 current 3 2 0 | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium Fuel | ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base >25 >20 >2.0 | <1 <1 <1 48 0 747 806 819 941 2059 <1 current 3 2 0 14.1 current | | |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED | ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) ASTM D7593* method ASTM D7844* | limit/base >25 >20 >2.0 limit/base >3 | <1 <1 48 0 747 806 819 941 2059 <1 current 3 2 0 14.1 | | history2 |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED Soot % | ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm | ASTM D5185(m) | limit/base >25 >20 >2.0 limit/base | <1 <1 48 0 747 806 819 941 2059 <1 current 3 2 0 14.1 current 0.8 | history1 history1 | history2 history2 |
| Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur Lithium CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED Soot % Nitration | ppm | ASTM D5185(m) ASTM D7593* method ASTM D7844* ASTM D7624* ASTM D7624* | limit/base >25 >20 >2.0 limit/base >3 >20 | <1 <1 <1 48 0 747 806 819 941 2059 <1 current 3 2 0 14.1 current 0.8 9.2 | history1 history1 | history2 history2 |



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number

: PC0081412 : 02589873

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Received Diagnosed : 5658939

: 19 Oct 2023 Diagnostician : Wes Davis

: 18 Oct 2023

Test Package : MOB 1 (Additional Tests: FuelDilution, KV40, PercentFuel, VI) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

ICSB - Brantford 567 Oak Park Rd. Brantford, ON CA N3T 5L8 Contact: Doug Hall Djhall@sharpbus.com T: (519)751-3434