

OIL ANALYSIS REPORT

Sample Rating Trend





Machine Id
Or1979
Component
Hydraulic System
Fluid
{not provided} (75 LTR)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. The oil change at the time of sampling has been noted. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please specify the component make and model with your next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear

Iron ppm levels are noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. All other component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.


Fluid Condition

The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		<u>-</u>		Apr2024	,	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0113384		
Sample Date		Client Info		01 Apr 2024		
Machine Age	hrs	Client Info		16204		
Oil Age	hrs	Client Info		16204		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METAL	_S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		8		
Iron	ppm	ASTM D5185(m)	>20	45		
Chromium	ppm	ASTM D5185(m)	>10	0		
Nickel	ppm	ASTM D5185(m)	>10	0		
Titanium	ppm	ASTM D5185(m)		<1		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>10	9		
Lead	ppm	ASTM D5185(m)	>10	0		
Copper	ppm	ASTM D5185(m)	>75	6		
Tin	ppm	ASTM D5185(m)	>10	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		96		
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		17		
Calcium	ppm	ASTM D5185(m)		3357		
Phosphorus	ppm	ASTM D5185(m)		688		
Zinc	ppm	ASTM D5185(m)		71		
Sulfur	ppm	ASTM D5185(m)		2592		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	27		
Sodium	ppm	ASTM D5185(m)		5		
Potassium	ppm	ASTM D5185(m)	>20	4		



OIL ANALYSIS REPORT



FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	113409		
Particles >6μm		ASTM D7647	>1300	41595		
Particles >14μm		ASTM D7647	>160	255		
Particles >21µm		ASTM D7647	>40	- 74		
Particles >38µm		ASTM D7647	>10	13		
Particles >71μm		ASTM D7647	>3	<u>^</u> 7		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	4 24/23/15		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	VLITE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>0.1	NEG		
Free Water	scalar	Visual*		NEG		
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)		56.0		
SAMPLE IMAG	ES	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number : 02626435 Unique Number : 5759567

: GFL0113384

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 720 - Lafleche - Landfill Received : 03 Apr 2024

Tested Diagnosed

: 04 Apr 2024 : 05 Apr 2024 - Kevin Marson Test Package : MOB 1 (Additional Tests: PQ, PrtCount)

CA K0C 1W0 Contact: Charles Bergeron cbergeron@gflenv.com T: (613)538-4853

17125 Lafleche Road,

Moose Creek, ON

Report Id: GFL720 [WCAMIS] 02626435 (Generated: 04/05/2024 11:45:28) Rev: 1

Submitted By: Charles Bergeron