

PROBLEM SUMMARY

Aft Machinery Space

Thruster Aft Center - Seal Oil System (S/N Sample Tag CL-06001-S3)


Sealing System


PETRO CANADA ENERGOL GR-XP ISO 150 (65 LTR)






COMPONENT CONDITION SUMMARY







RECOMMENDATION

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you change the oil. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE	SEVERE	SEVERE	
Water	%	ASTM D6304*		△ 0.655	△ 0.392	△ 0.483	
ppm Water	ppm	ASTM D6304*		△ 6553	△ 3923	<u></u> 4837	
Particles >4µm		ASTM D7647	>5000	164408	1 19034	▲ 106205	
Particles >6µm		ASTM D7647	>1300	39507	▲ 50347	2 4198	
Oil Cleanliness		ISO 4406 (c)	>19/17/14	25/22/13	4 24/23/19	4 24/22/17	
Precipitate	scalar	Visual*	NONE	MODER	NONE	NONE	
Appearance	scalar	Visual*	NORML	▲ WGOIL	▲ LAYRD	WGOIL	
Emulsified Water	scalar	Visual*		. 5%	<u> </u>	<u> </u>	
Free Water	scalar	Visual*		<u></u> >10%	<u></u> >10%	NEG	
Viscosity Index (VI)	Scale	ASTM D2270*		4 75	▲ 175	87	

Customer Id: TERHAM Sample No.: PC Lab Number: 02634783 Test Package: MAR 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you change the oil.		
Change Filter			?	We recommend you service the filters on this component.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Water Access			?	We advise that you check for the source of water entry.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		

HISTORICAL DIAGNOSIS

26 Feb 2024 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this fluid. We advise that you follow the water drain-off procedure for this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the fluid. There is a moderate concentration of water present in the fluid. Free water present. The AN level is acceptable for this fluid.



04 Jan 2024 Diag: Bill Quesnel





Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this fluid. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the fluid. There is a moderate concentration of water present in the fluid. The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



14 Sep 2023 Diag: Bill Quesnel





We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the fluid. The water content is negligible. The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

Area

Aft Machinery Space

Thruster Aft Center - Seal Oil System (S/N Sample Tag CL-06001-S3)

Sealing System

Fluid

PETRO CANADA ENERGOL GR-XP ISO 150 (65 LTR)





DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you change the oil. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the fluid. There is a moderate concentration of water present in the fluid. Excessive free water present. Abnormal water content and sodium(Na) level indicate possible sea water contamination.

Fluid Condition

The white residue present in the sample is fluid additive precipitate. The AN level is acceptable for this fluid. The fluid is no longer serviceable due to the presence of contaminants.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC	PC0082728	PC
Sample Date		Client Info		21 Apr 2024	26 Feb 2024	04 Jan 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METALS	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>100	13	14	15
Chromium	ppm	ASTM D5185(m)	>3	<1	<1	<1
Nickel	ppm	ASTM D5185(m)	>8	0	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>3	<1	<1	<1
Lead	ppm	ASTM D5185(m)		0	0	0
Copper	ppm	ASTM D5185(m)	>3	<1	<1	<1
Tin	ppm	ASTM D5185(m)		0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		1	<1	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		6	4	4
Calcium	ppm	ASTM D5185(m)		6	5	6
Phosphorus	ppm	ASTM D5185(m)		111	138	173
Zinc	ppm	ASTM D5185(m)		8	12	10
Sulfur	ppm	ASTM D5185(m)		7679	8434	8297
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	2	4	4
Sodium	ppm	ASTM D5185(m)		38	25	21
Potassium	ppm	ASTM D5185(m)	>20	2	2	2
Water	%	ASTM D6304*		△ 0.655	△ 0.392	△ 0.483
ppm Water	ppm	ASTM D6304*		△ 6553	▲ 3923	▲ 4837
FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	164408	1 19034	▲ 106205
Particles >6µm		ASTM D7647	>1300	39507	▲ 50347	2 4198
Particles >14µm		ASTM D7647	>160	68	4544	4 946
Particles >21µm		ASTM D7647	>40	10	▲ 553	<u> </u>
Particles >38µm		ASTM D7647	>10	0	7	2

0

24/23/19

Contact/Location: Josh Hynes - TERHAM

ISO 4406 (c) >19/17/14 **25/22/13**

ASTM D7647 >3

Particles >71µm


Oil Cleanliness




35000 30000


10000

OIL ANALYSIS REPORT



FLUID DEGRAD	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.9	0.32	0.32	0.36
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	MODER	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	▲ WGOIL	▲ LAYRD	WGOIL
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*		. 5%	<u>1</u> %	<u>.5%</u>
Free Water	scalar	Visual*		<u></u> >10%	<u></u> >10%	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	149	143	143	142
Visc @ 100°C	cSt	ASTM D7279(m)	14.5	12.7	21.4	13.4
Viscosity Index (VI)	Scale	ASTM D2270*		<u> </u>	△ 175	87
SAMPLE IMAG	ES	method	limit/base	current	history1	history2
Color						







CALA ISO 17025:2017 Accredited Laboratory

Laboratory

Sample No. Lab Number : 02634783 Unique Number : 5775936

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 10 May 2024

: PC Received **Tested**

: 14 May 2024 Diagnosed

: 15 May 2024 - Kevin Marson Test Package : MAR 2 (Additional Tests: Bottom, KF, KV100, PQ, PrtCount, TAN Man, VI)

joshynes@suncor.com T: (709)778-3575

Contact: Josh Hynes

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Bottom

F: (709)724-2835

Suncor - Terra Nova Projects

Scotia Centre, 235 Water Strret

St. John's, NL

CA A1C 1B6