

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

BUSCH VAC PUMP

Gearbox Fluid VSB 100 (--- LTR)

DIAGNOSIS

A Recommendation

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of water present in the oil. Free water present.


Fluid Condition


The AN level is acceptable for this fluid. The oil is no longer serviceable due to the presence of contaminants.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC0087803		
Sample Date		Client Info		22 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS	5	method	limit/base	current	history1	history2
PQ		ASTM D8184*		27		
Iron	ppm	ASTM D5185(m)	>200	3		
Chromium	ppm	ASTM D5185(m)	>15	0		
Nickel	ppm	ASTM D5185(m)	>15	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	<1		
Lead	ppm	ASTM D5185(m)	>100	0		
Copper	ppm	ASTM D5185(m)	>200	<1		
Tin	ppm	ASTM D5185(m)	>25	0		
Antimony	ppm	ASTM D5185(m)	>5	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		1		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		0		
Calcium	ppm	ASTM D5185(m)		0		
Phosphorus	ppm	ASTM D5185(m)		10		
Zinc	ppm	ASTM D5185(m)		<1		
Sulfur	ppm	ASTM D5185(m)		713		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINAN	ΓS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	<1		
Sodium	ppm	ASTM D5185(m)		2		
Potassium	ppm	ASTM D5185(m)	>20	<1		
Water	%	ASTM D6304*	>0.2	<u> </u>		
www.Mater	ppm	ASTM D6304*	>2000	<u> </u>		
ppm Water						
FLUID DEGRAD		method	limit/base	current	history1	history2



OIL ANALYSIS REPORT







To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Report Id: TAVTAV [WCAMIS] 02647437 (Generated: 07/16/2024 08:32:10) Rev: 1

CALA

ISO 17025:2017 Accredited

Laboratory

Laboratory

Sample No.

Lab Number

Contact/Location: Brian Schwartzentruber - TAVTAV

T: (519)655-2337

F: (519)655-3449