


# **PROBLEM SUMMARY**

•



731115 Component

**Transmission (Auto)** 

PETRO CANADA DuraDrive HD Synthetic 668 (--- GAL)

# **COMPONENT CONDITION SUMMARY**

No relevant graphs to display

### RECOMMENDATION

We suspect abnormal metal contamination may be due to sampling method. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status				ABNORMAL	NORMAL	ABNORMAL			
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	▲ MODER			

Customer Id: GFL836 Sample No.: GFL0087236 Lab Number: 05894834 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

# HISTORICAL DIAGNOSIS

14 Feb 2023 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### 26 Jul 2022 Diag: Jonathan Hester

**VISUAL METAL** 



We suspect abnormal metal contamination may be due to sampling method. No corrective action is recommended at this time. Resample at the next service interval to monitor. Moderate concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.





# **OIL ANALYSIS REPORT**

Sample Rating Trend **VISUAL METAL** 



Machine Id 731115

Component **Transmission (Auto)** 

**PETRO CANADA DuraDrive HD Synthetic** 

# **DIAGNOSIS**

### Recommendation

We suspect abnormal metal contamination may be due to sampling method. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

# Wear

Moderate concentration of visible metal present. All component wear rates are normal.

### Contamination

There is no indication of any contamination in the fluid.

### **Fluid Condition**


The condition of the fluid is acceptable for the time in service.

668 ( GAL)		Ju	12022	Feb 2023 Jul 20	28	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0087236	GFL0070306	GFL0050600
Sample Date		Client Info		07 Jul 2023	14 Feb 2023	26 Jul 2022
Machine Age	hrs	Client Info		5214	4454	3279
Oil Age	hrs	Client Info		1200	1200	3274
Oil Changed		Client Info		Changed	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	ABNORMAL
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>160	119	134	100
Chromium	ppm	ASTM D5185m	>5	<1	0	0
Nickel	ppm	ASTM D5185m	>5	<1	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m	>5	0	0	0
Aluminum	ppm	ASTM D5185m	>50	34	31	21
_ead	ppm	ASTM D5185m	>50	8	9	7
Copper	ppm	ASTM D5185m	>225	34	23	17
Tin	ppm	ASTM D5185m	>10	6	5	3
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		78	91	99
Barium	ppm	ASTM D5185m		0	0	<1
Molybdenum	ppm	ASTM D5185m		2	1	1
Manganese	ppm	ASTM D5185m		3	4	3
Magnesium	ppm	ASTM D5185m		5	4	<1
Calcium	ppm	ASTM D5185m		61	53	43
Phosphorus	ppm	ASTM D5185m		238	248	238
Zinc	ppm	ASTM D5185m		0	18	5
Sulfur	ppm	ASTM D5185m		999	718	981
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6	7	7
Sodium	ppm	ASTM D5185m		7	6	4
Potassium	ppm	ASTM D5185m	>20	5	2	4
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	▲ MODER
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2

35.1



# **OIL ANALYSIS REPORT**





Laboratory Sample No. Lab Number

: 05894834 Unique Number : 10550644

: GFL0087236

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 11 Jul 2023 Diagnosed

: 20 Jul 2023 Diagnostician : Doug Bogart

**Test Package**: FLEET (Additional Tests: FT-IR, KV100, TBN) To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 836 - Kansas City Hauling

7801 East Truman Road Kansas City, MO US 64126 Contact: Robert Hart

rhart@gflenv.com

T: (580)461-1509