

PROBLEM SUMMARY

Sample Rating Trend

DEGRADATION

VOLVO VNL 760 224

Component

Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- GAL)

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ABNORMAL					
Base Number (BN)	mg KOH/g	ASTM D2896	<u></u> 1.8					

Customer Id: ATRPIN Sample No.: PCA0100615 Lab Number: 05897867 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend

DEGRADATION

VOLVO VNL 760 224

Component

Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition


The BN level is low.


AL)				Jul2023		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0100615		
Sample Date		Client Info		06 Jul 2023		
Machine Age	mls	Client Info		86215		
Oil Age	mls	Client Info		43623		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>6.0	<1.0		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	70		
Chromium	ppm	ASTM D5185m	>20	1		
Nickel	ppm	ASTM D5185m	>2	<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>2	<1		
Aluminum	ppm	ASTM D5185m	>25	16		
Lead	ppm	ASTM D5185m	>40	<1		
Copper	ppm	ASTM D5185m	>330	55		
Tin	ppm	ASTM D5185m	>15	3		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	2		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	50	72		
Manganese	ppm	ASTM D5185m	0	2		
Magnesium	ppm	ASTM D5185m	950	861		
Calcium	ppm	ASTM D5185m	1050	1165		
Phosphorus	ppm	ASTM D5185m	995	968		
Zinc	ppm	ASTM D5185m	1180	1186		
Sulfur	ppm	ASTM D5185m	2600	2589		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	11		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	42		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	8.0		
Nitration	Abs/cm	*ASTM D7624	>20	14.7		
Sulfation	Abs/.1mm	*ASTM D7415	>30	27.7		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	29.5		
Base Number (BN)	mg KOH/g	ASTM D2896		<u> </u>		




OIL ANALYSIS REPORT











Certificate L2367

Laboratory Sample No.

Lab Number Unique Number

: PCA0100615 : 05897867 : 10559223 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Jul 2023 Diagnosed : 17 Jul 2023 Diagnostician

: Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

A Truck Repair 9349 China Grove Church Road

Pineville, NC US 28134

Contact: Vlad Melnichuk shop@migway.com T: (980)255-3200

history2

history2