


### **PROBLEM SUMMARY**


# PROCESS CHEESE [98316341] Machine Id SOUTH/SOUTH SCREW FEED


Component **Gearbox** 

GEAR OIL ISO 320 (--- GAL)



### **COMPONENT CONDITION SUMMARY**





### RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Silicon	ppm	ASTM D5185m	>50	<u>^</u> 50				
Particles >4µm		ASTM D7647	>1300	<b>91224</b>				
Particles >6µm		ASTM D7647	>320	<u> </u>				
Particles >14µm		ASTM D7647	>80	<b>△</b> 672				
Particles >21µm		ASTM D7647	>20	<u> </u>				
Particles >38µm		ASTM D7647	>4	<u> </u>				
Oil Cleanliness		ISO 4406 (c)	>17/15/13	<u>4</u> 24/21/17				

Customer Id: KRASPRMO Sample No.: PCA0100118 Lab Number: 05898565 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component if applicable.			

## HISTORICAL DIAGNOSIS




### **OIL ANALYSIS REPORT**

# PROCESS CHEESE [98316341] SOUTH/SOUTH SCREW FEED

Component

Gearbox

GEAR OIL ISO 320 (--- GAL)





### **DIAGNOSIS**

### Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is a high amount of particulates present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material.


### **Fluid Condition**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Jul2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0100118		
Sample Date		Client Info		08 Jul 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	38		
Chromium	ppm	ASTM D5185m	>15	<1		
Nickel	ppm	ASTM D5185m	>15	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	0		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	0		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	50	0		
Barium	ppm	ASTM D5185m	15	0		
Molybdenum	ppm	ASTM D5185m	15	0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	50	3		
Calcium	ppm	ASTM D5185m	50	0		
Phosphorus	ppm	ASTM D5185m	350	42		
Zinc	ppm	ASTM D5185m	100	0		
Sulfur	ppm	ASTM D5185m	12500	4		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	<b>5</b> 0		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	2		
FLUID CLEANI	LINESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>1300	<u> </u>		
Particles >6µm		ASTM D7647	>320	<u> </u>		
Particles >14μm		ASTM D7647	>80	<b>△</b> 672		
Particles >21µm		ASTM D7647	>20	<u> </u>		
Particles >38µm		ASTM D7647	>4	<u>^</u> 6		
Particles >71µm		ASTM D7647	>3	2		
Oil Cleanliness		ISO 4406 (c)	>17/15/13	<u>4</u> 24/21/17		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.85	0.13		



### **OIL ANALYSIS REPORT**





Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: PCA0100118 : 05898565

: 10559921

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jul 2023

Diagnosed : 17 Jul 2023 Diagnostician : Jonathan Hester

Test Package : IND 2 ( Additional Tests: PrtCount )

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

KraftHeinz - Springfield - Plant 8311 PCA

2035 E BENNETT SPRINGFIELD, MO

US 65804

Contact: Service Manager

T: F: