

PROBLEM SUMMARY











Machine Id 426139 Component 2 Differential Fluid

GEAR OIL SAE 75W90 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. (Customer Sample Comment: 2nd / Tag)

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	 	
Aluminum	ppm	ASTM D5185m	>25	△ 32	 	
Silicon	mqq	ASTM D5185m	>75	93	 	

Customer Id: GFL983 Sample No.: GFL0085454 Lab Number: 05900311 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Check Dirt Access			?	We advise that you check all areas where dirt can enter the system.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT





Machine Id 426139 Component 2 Differential

GEAR OIL SAE 75W90

DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. (Customer Sample Comment: 2nd / Tag)

Wear

All component wear rates are normal.

Contamination

Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress.


Fluid Condition

The condition of the oil is acceptable for the time in service.

(GAL)				Jul2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0085454		
Sample Date		Client Info		11 Jul 2023		
Machine Age	mls	Client Info		217792		
Dil Age	mls	Client Info		217792		
Oil Changed	11110	Client Info		Changed		
Sample Status		Onorte milo		ABNORMAL		
WEAR METAL	S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>500	332		
Chromium	ppm	ASTM D5185m	>10	3		
Nickel	ppm	ASTM D5185m	>10	<1		
itanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	△ 32		
_ead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>100	2		
Fin	ppm	ASTM D5185m	>100	<1		
/anadium	ppm	ASTM D5185m	>10	0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	400	197		
Barium	ppm	ASTM D5185m	200	<1		
Nolybdenum	ppm	ASTM D5185m	12	<1		
Manganese	ppm	ASTM D5185m	. —	13		
Magnesium	ppm	ASTM D5185m	12	0		
Calcium	ppm	ASTM D5185m	150	22		
Phosphorus	ppm	ASTM D5185m	1650	1258		
Zinc	ppm	ASTM D5185m	125	22		
Sulfur	ppm	ASTM D5185m	22500	22042		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	△ 93		
Sodium	ppm	ASTM D5185m		4		
Potassium	ppm	ASTM D5185m	>20	4		
VISUAL		method	limit/base	current	history1	history
Vhite Metal	scalar	*Visual	NONE	MODER		
'ellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
	scalar scalar	*Visual	>.2	NEG NEG		



OIL ANALYSIS REPORT





Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10561667 Test Package : FLEET

: GFL0085454 : 05900311

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 17 Jul 2023 Received Diagnosed : 19 Jul 2023 Diagnostician : Sean Felton

GFL Environmental - 983 - Sugar Land Hauling 16011 West Belfort Street

Sugar Land, TX US 77498

Contact: TECHNICIAN ACCOUNT

wcgfldemo@gmail.com

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) T:

F: