

PROBLEM SUMMARY

Sample Rating Trend

SOOT





FREIGHTLINER 104

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (13 LTR)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check for faulty combustion, plugged air filters, or aftercoolers. We recommend an early resample to monitor this condition. NOTE: High solids (carbon/soot) in the sample have limited the accuracy of Infra-Red data including Total Base Number (TBN) value.

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE			
Soot %	%	*ASTM D7844	>3	6			
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	△ 0.0			
Visc @ 100°C	cSt	ASTM D445	15.4	A 29.1			

Customer Id: ATRPIN Sample No.: PCA0100673 Lab Number: 05902069 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Resample			?	We recommend an early resample to monitor this condition.		
Alert			?	NOTE: High solids (carbon/soot) in the sample have limited the accuracy of Infra-Red data including Total Base Number (TBN) value.		
Check Combustion			?	We advise that you check for faulty combustion, plugged air filters, or aftercoolers.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

FREIGHTLINER 104

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (13 LTR)

DIAGNOSIS

Recommendation

We advise that you check for faulty combustion, plugged air filters, or aftercoolers. We recommend an early resample to monitor this condition. NOTE: High solids (carbon/soot) in the sample have limited the accuracy of Infra-Red data including Total Base Number (TBN) value.

Wear

All component wear rates are normal.

Contamination

There is an abnormal amount of solids and carbon present in the oil.

▲ Fluid Condition


The oil viscosity is higher than normal. The BN level is low. The oil is no longer serviceable due to the presence of contaminants.

Samp	le Rating Trend		S	оот
	Jul 20	3		3
method	limit/base	current	history1	hietory2

- i n <i>)</i>				Jul2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0100673		
Sample Date		Client Info		17 Jul 2023		
Machine Age	mls	Client Info		343453		
Oil Age	mls	Client Info		29753		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	45		
Chromium	ppm	ASTM D5185m	>5	3		
Nickel	ppm	ASTM D5185m	>2	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m	>30	<1		
Lead	ppm	ASTM D5185m	>30	13		
Copper	ppm	ASTM D5185m	>150	2		
Tin	ppm	ASTM D5185m	>5	<1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	60	56		
Manganese	ppm	ASTM D5185m	0	<1		
Magnesium	ppm	ASTM D5185m	1010	838		
Calcium	ppm	ASTM D5185m	1070	1129		
Phosphorus	ppm	ASTM D5185m	1150	906		
Zinc	ppm	ASTM D5185m	1270	1081		
Sulfur	ppm	ASTM D5185m	2060	3069		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	6		
Sodium	ppm	ASTM D5185m		4		
Potassium	ppm	ASTM D5185m	>20	0		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	6		
Nitration	Abs/cm	*ASTM D7624	>20	16.4		
Sulfation	Abs/.1mm	*ASTM D7415	>30	37.2		
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	26.5		
Base Number (BN)	mg KOH/g		9.8	<u> </u>		
. ,						



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number Unique Number

: 05902069 : 10563425 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0100673 Received : 19 Jul 2023 Diagnosed : 20 Jul 2023

: Don Baldridge Diagnostician

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

9349 China Grove Church Road Pineville, NC US 28134

Contact: Vlad Melnichuk shop@migway.com

T: (980)255-3200