


# **PROBLEM SUMMARY**







Machine Id **222040**Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

## **COMPONENT CONDITION SUMMARY**





#### RECOMMENDATION

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS										
Sample Status				ABNORMAL	ABNORMAL	NORMAL				
Fuel	%	ASTM D3524	>5	<b>△</b> 5.4	<b>4.2</b>	<1.0				
Visc @ 100°C	cSt	ASTM D445	15.4	<b>12.4</b>	A 12.2	12.8				

Customer Id: GFL912 Sample No.: GFL0072502 Lab Number: 05918400 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.

## HISTORICAL DIAGNOSIS

17 Jan 2023 Diag: Jonathan Hester





We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.



04 Aug 2022 Diag: Don Baldridge

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**









Machine Id 222040 Component **Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

### **DIAGNOSIS**

#### Recommendation

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

All component wear rates are normal.

#### Contamination

There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.


#### Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

N SHP 15W40 (	- GAL)	Aug	2022	Jan 2023 Jul 202	13	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0072502	GFL0072512	GFL0055989
Sample Date		Client Info		25 Jul 2023	17 Jan 2023	04 Aug 2022
Machine Age	hrs	Client Info		15832	3505	2789
Oil Age	hrs	Client Info		604	600	0
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	31	31	22
Chromium	ppm	ASTM D5185m	>5	1	<1	<1
Nickel	ppm	ASTM D5185m	>2	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>30	3	3	5
Lead	ppm	ASTM D5185m	>30	0	0	0
Copper	ppm	ASTM D5185m	>150	0	<1	<1
Tin	ppm	ASTM D5185m	>5	<1	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	12	132	178
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	74	117	89
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	1032	532	459
Calcium	ppm	ASTM D5185m	1070	1224	1367	1522
Phosphorus	ppm	ASTM D5185m	1150	1025	571	651
Zinc	ppm	ASTM D5185m	1270	1344	730	803
Sulfur	ppm	ASTM D5185m	2060	3552	2032	2231
CONTAMINAN	TS	method	limit/base	current	history1	history2
				Current	Thistory	
Silicon	ppm	ASTM D5185m		4	5	5
	ppm ppm	ASTM D5185m ASTM D5185m				
Sodium				4	5	5
Sodium Potassium	ppm	ASTM D5185m	>20	4 50	5 15	5
Sodium Potassium	ppm ppm	ASTM D5185m ASTM D5185m	>20 >20	4 50 2	5 15 4	5 0 1
Sodium Potassium Fuel INFRA-RED	ppm ppm	ASTM D5185m ASTM D5185m ASTM D3524	>20 >20 >5	4 50 2 ▲ 5.4	5 15 4 • 4.2	5 0 1 <1.0
Sodium Potassium Fuel INFRA-RED Soot %	ppm ppm %	ASTM D5185m ASTM D5185m ASTM D3524 method	>20 >20 >5 limit/base >3	4 50 2 • 5.4 current	5 15 4 ▲ 4.2 history1	5 0 1 <1.0 history2
Sodium Potassium Fuel INFRA-RED Soot % Nitration	ppm ppm %	ASTM D5185m ASTM D5185m ASTM D3524 method *ASTM D7844	>20 >20 >5 limit/base >3	4 50 2 ▲ 5.4 current 0.3	5 15 4 ▲ 4.2 history1	5 0 1 <1.0 history2 0.2
Sodium Potassium Fuel INFRA-RED Soot % Nitration	ppm ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D7415	>20 >20 >5 limit/base >3 >20	4 50 2 ▲ 5.4 current 0.3 10.2	5 15 4 ▲ 4.2 history1 0.4 8.8	5 0 1 <1.0 history2 0.2 10.0
Soot % Nitration Sulfation	ppm ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D7415	>20 >20 >5 limit/base >3 >20 >30	4 50 2 5.4 current 0.3 10.2 21.3	5 15 4 4.2 history1 0.4 8.8 19.9	5 0 1 <1.0 history2 0.2 10.0 24.1
Sodium Potassium Fuel INFRA-RED Soot % Nitration Sulfation FLUID DEGRAI	ppm ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D7415 method	>20 >20 >5 limit/base >3 >20 >30 limit/base >35	4 50 2 ▲ 5.4 current 0.3 10.2 21.3 current	5 15 4 A.2 history1 0.4 8.8 19.9 history1	5 0 1 <1.0 history2 0.2 10.0 24.1 history2



# **OIL ANALYSIS REPORT**







Laboratory Sample No. Lab Number

**Unique Number** : 10590314 Test Package : FLEET ( Additional Tests: PercentFuel )

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 08 Aug 2023 : GFL0072502 : 09 Aug 2023 Diagnosed : 05918400

Diagnostician : Wes Davis

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 912 - Fort Atkinson HC

7/23

1215 Klement St. Fort Atkinson, WI US 53538

Contact: LEONARD KOZLEUCHAR leonard.kozleuchar@gflenv.com

T: (262)210-6528

F: