

PROBLEM SUMMARY

Sample Rating Trend

VISUAL METAL





Machine Id 10863

Component
Transmission (Auto)

PETRO CANADA DuraDrive HD Synthetic 668 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of metal. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	NORMAL	NORMAL		
Molybdenum	ppm	ASTM D5185m		^ 25	<1	0		
Magnesium	ppm	ASTM D5185m		△ 301	5	<1		
Calcium	ppm	ASTM D5185m		<u></u> 524	121	121		
Zinc	ppm	ASTM D5185m		4 359	23	27		
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	NONE		
Visc @ 40°C	cSt	ASTM D445	34	51.7	36.1	33.6		

Customer Id: GFL010 Sample No.: GFL0088759 Lab Number: 05922570 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

17 Mar 2023 Diag: Don Baldridge





Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



03 Mar 2023 Diag: Sean Felton

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

View report

13 Feb 2023 Diag: Angela Borella

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample Rating Trend



VISUAL METAL



Machine Id 10863 Component

Transmission (Auto)

PETRO CANADA DuraDrive HD Synthetic 668 (--- GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of metal. Resample at the next service interval to monitor.

Wear

Moderate concentration of visible metal present. All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid.


▲ Fluid Condition

The fluid viscosity is higher than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.


668 (GAL)		Aug2022	Nov2022 Jan2023	Feb2023 Mar2023 Mar2023	Aug2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0088759	GFL0062596	GFL0062547
Sample Date		Client Info		04 Aug 2023	17 Mar 2023	03 Mar 2023
Machine Age	hrs	Client Info		40186	13854	13714
Oil Age	hrs	Client Info		1375	433	501
Oil Changed		Client Info		Changed	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>160	33	59	51
Chromium	ppm	ASTM D5185m	>5	<1	0	0
Nickel	ppm	ASTM D5185m	>5	<1	0	0
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m	>5	0	0	0
Aluminum	ppm	ASTM D5185m	>50	5	5	3
Lead	ppm	ASTM D5185m	>50	2	0	0
Copper	ppm	ASTM D5185m	>225	12	4	3
Tin	ppm	ASTM D5185m	>10	<1	<1	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		87	65	63
Barium	ppm	ASTM D5185m		1	0	0
Molybdenum	ppm	ASTM D5185m		4 25	<1	0
Manganese	ppm	ASTM D5185m		<1	1	0
Magnesium	ppm	ASTM D5185m		301	5	<1
Calcium	ppm	ASTM D5185m		524	121	121
Phosphorus	ppm	ASTM D5185m		413	207	209
Zinc	ppm	ASTM D5185m		4 359	23	27
Sulfur	ppm	ASTM D5185m		1917	1573	1632
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	7	6	4
Sodium	ppm	ASTM D5185m		4	3	0
Potassium	ppm	ASTM D5185m	>20	1	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	VLITE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2




OIL ANALYSIS REPORT









GRAPHS











Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 10602517

: GFL0088759 : 05922570 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 11 Aug 2023 Diagnosed : 14 Aug 2023 Diagnostician : Don Baldridge

GFL Environmental - 010 - Stockbridge

1280 Rum Creek Parkway Stockbridge, GA US 30281

Contact: JOSHUA TINKER joshuatinker@gflenv.com

T:

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: