

PROBLEM SUMMARY

Sample Rating Trend

WEAR

WEAR


Machine Id **822005-190**


Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- LTR)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status				ABNORMAL	NORMAL	NORMAL			
Iron	ppm	ASTM D5185m	>80	<u> </u>	71	53			
Soot %	%	*ASTM D7844	>3	A 3.4	22	1 7			

Customer Id: GFL654S Sample No.: GFL0089523 Lab Number: 05922644 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

05 May 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



21 Mar 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



22 Feb 2023 Diag: Wes Davis

NORMAL




Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



WEAR

822005-190

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- L'

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

Cylinder, crank, or cam shaft wear is indicated. All other component wear rates are normal.

Contamination

There is an abnormal amount of solids and carbon present in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

_TR)		Feb 2022 F	eb2022 Apr2022	Apr2022 Oct2022 Mar2023	Aug2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0089523	GFL0067888	GFL0067961
Sample Date		Client Info		07 Aug 2023	05 May 2023	21 Mar 2023
Machine Age	hrs	Client Info		11987	65615	11529
Oil Age	hrs	Client Info		1044	65615	11529
Oil Changed		Client Info		Changed	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	<u> </u>	71	53
Chromium	ppm	ASTM D5185m	>5	3	2	2
Nickel	ppm	ASTM D5185m	>2	1	<1	0
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>30	6	3	4
Lead	ppm	ASTM D5185m	>30	6	4	2
Copper	ppm	ASTM D5185m	>150	4	3	2
Tin	ppm	ASTM D5185m	>5	2	<1	<1
Vanadium	ppm	ASTM D5185m		<1	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	4	4	4
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	67	66	63
Manganese	ppm	ASTM D5185m	0	1	<1	1
Magnesium	ppm	ASTM D5185m	1010	1024	957	958
Calcium	ppm	ASTM D5185m	1070	1160	1135	1150
Phosphorus	ppm	ASTM D5185m	1150	1099	1047	998
Zinc	ppm	ASTM D5185m	1270	1375	1316	1300
Sulfur	ppm	ASTM D5185m	2060	3446	3084	3000
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	15	14	11
Sodium	ppm	ASTM D5185m		11	8	8
Potassium	ppm	ASTM D5185m	>20	11	9	6
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	▲ 3.4	2.2	1.7
Nitration	Abs/cm	*ASTM D7624	>20	18.2	13.6	12.6
Sulfation	Abs/.1mm	*ASTM D7415	>30	32.3	25.4	24.3
FLUID DEGRAD	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	29.6	22.6	20.4
Oxidation	AUS/.TITIIII	AUTIVIDITIT	720	29.0	22.0	20.7



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number

Unique Number

: GFL0089523 : 05922644 : 10602591 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 11 Aug 2023

Diagnosed : 14 Aug 2023 : Don Baldridge Diagnostician

12230 Deergrove Road Midlothian, VA US 23112 Contact: Corbin Umphlet

cumphlet@gflenv.com T:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: GFL654S [WUSCAR] 05922644 (Generated: 08/14/2023 13:17:08) Rev: 1

GFL Environmental - 654S - Midlothian

F: