


# **PROBLEM SUMMARY**

Prea [97466102]


KR-GR-003426 - LOG REJECT CONVEYOR (S/N STUFF C - 11519781)

Gearbox

MOBIL GLYGOYLE HE ISO 460 (--- GAL)



## **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL			
Iron	ppm	ASTM D5185m	>200	<b>△</b> 503			

**Customer Id: KRAKIR** Sample No.: PCA0101929 Lab Number: 05925189 Test Package: IND 1 To manage this report scan the QR code To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Resample			?	We recommend an early resample to monitor this condition.		

# HISTORICAL DIAGNOSIS



# **OIL ANALYSIS REPORT**

SAMPLE INFORMATION

## **WEAR**



# Area [97466102]

# KR-GR-003426 - LOG REJECT CONVEYOR (S/N STUFF C - 11519781)

Gearbox

MOBIL GLYGOYLE HE ISO 460 (--- GAL)

### **DIAGNOSIS**

### Recommendation

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

### Wear

Gear wear is indicated.

### Contamination

There is no indication of any contamination in the

### **Fluid Condition**


The condition of the oil is acceptable for the time in

- Сир.	e Rating Trend		
Ī			
	Aug 202	23	
	limit/base		

SAMI LL IN OTT	VIATION		IIIIIII Dase	Culletti	Thistory	HISTOLYZ
Sample Number		Client Info		PCA0101929		
Sample Date		Client Info		09 Aug 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	<b>503</b>		
Chromium	ppm	ASTM D5185m	>15	6		
Nickel	ppm	ASTM D5185m	>15	<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	0		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	0		
Tin	ppm	ASTM D5185m	>25	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		2		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		7		
Phosphorus	ppm	ASTM D5185m		172		
Zinc	ppm	ASTM D5185m		44		
Sulfur	ppm	ASTM D5185m		1119		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	2		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	3		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Free Water	scalar	*Visual		NEG		
FLUID PROPE	RTIES	method	limit/base	current	history1	history2



# **OIL ANALYSIS REPORT**





Certificate L2367

Laboratory Sample No. Lab Number

: PCA0101929 : 05925189 Unique Number : 10605136 Test Package : IND 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 15 Aug 2023 Diagnosed : 16 Aug 2023

Diagnostician : Doug Bogart

KraftHeinz - Kirksville - Plant 8333 PCA 2504 INDUSTRIAL DR

KIRKSVILLE, MO US 63501

Contact: WALLACE WARD wallace.ward@kraftheinzcompany.com

T: (660)627-1031 F: (660)627-5887

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)