

PROBLEM SUMMARY

Sample Rating Trend




[98347721]

KR-GR-003114 - EAST DUMPER (S/N MIX D - 11513073)

Component


Hydraulic System

AW HYDRAULIC OIL ISO 68 (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status			ABNORMAL	ABNORMAL	ABNORMAL
Particles >4µm	ASTM D7647	>10000	27738	43868	<u>^</u> 27091
Oil Cleanliness	ISO 4406 (c)	>20/18/16	22/17/11	23/19/15	22/19/15

Customer Id: KRAKIR Sample No.: PCA0101718 Lab Number: 05926085 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.

HISTORICAL DIAGNOSIS

31 Jul 2023 Diag: Don Baldridge





We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.



31 May 2023 Diag: Angela Borella

ISO



We recommend you service the filters on this component. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

view report

02 May 2023 Diag: Angela Borella

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.






OIL ANALYSIS REPORT

Area [98347721]

KR-GR-003114 - EAST DUMPER (S/N MIX D - 11513073)

Hydraulic System

AW HYDRAULIC OIL ISO 68 (--- GAL)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

		12020 140020	20 Mar2021 Aug2021	Jan2022 Jun2022 Oct2022 A	pr2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0101718	PCA0103231	PCA0073083
Sample Date		Client Info		31 Jul 2023	31 Jul 2023	31 May 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<1	1	<1
Chromium	ppm	ASTM D5185m	>20	<1	<1	0
Nickel	ppm	ASTM D5185m	>20	0	<1	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	0	0	<1
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	0	0	0
Tin	ppm	ASTM D5185m	>20	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	0	0
Barium	ppm	ASTM D5185m	5	<1	0	1
Molybdenum	ppm	ASTM D5185m	5	0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m	25	0	0	0
Calcium	ppm	ASTM D5185m	200	2	<1	0
Phosphorus	ppm	ASTM D5185m	300	412	400	361
Zinc	ppm	ASTM D5185m	370	0	0	0
Sulfur	ppm	ASTM D5185m	2500	473	464	478
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	2	2	2
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	<1	<1	0
FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	27738	<u>43868</u>	△ 27091
Particles >6µm		ASTM D7647	>2500	1173	4499	▲ 3650
Particles >14µm		ASTM D7647	>640	11	167	180
Particles >21µm		ASTM D7647	>160	3	26	32
Particles >38µm		ASTM D7647	>40	0	1	0
Particles >71μm		ASTM D7647	>10	0	1	0
Oil Cleanliness		ISO 4406 (c)	>20/18/16	<u>22/17/11</u>	<u>\$\text{\Delta}\$ 23/19/15</u>	<u>22/19/15</u>

mg KOH/g ASTM D8045 0.57

Acid Number (AN)


0.19

0.20

0.12



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number**

: 05926085 : 10606032 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0101718 Received Diagnosed

: 16 Aug 2023 : 17 Aug 2023 : Don Baldridge Diagnostician

wallace.ward@kraftheinzcompany.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (660)627-1031 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (660)627-5887

2504 INDUSTRIAL DR

Contact: WALLACE WARD

KIRKSVILLE, MO

US 63501

KraftHeinz - Kirksville - Plant 8333 PCA

Report Id: KRAKIR [WUSCAR] 05926085 (Generated: 08/17/2023 15:11:43) Rev: 1

Contact/Location: WALLACE WARD - KRAKIR