


OIL ANALYSIS REPORT



KEMP QUARRIES / PRYOR STONE [65064] **ÖHT058**

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)





DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. (Customer Sample Comment: Pm3 performed. All oil samples taken. Engine oil, and all filters changed.)

Wear

The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core).

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0084057	PCA0083982	PCA0049013
Sample Date		Client Info		09 Aug 2023	05 May 2023	07 Nov 2022
Machine Age	hrs	Client Info		51041	50583	50124
Oil Age	hrs	Client Info		458	459	623
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	31	39	30
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>2	<1	<1	0
Titanium	ppm	ASTM D5185m	>2	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>25	3	2	1
Lead	ppm	ASTM D5185m	>40	2	10	2
Copper	ppm	ASTM D5185m	>330	<u>▲</u> 533	283	△ 599
Tin	ppm	ASTM D5185m	>15	<1	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	3	11	6
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	59	56	71
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	916	761	998
Calcium	ppm	ASTM D5185m	1070	1047	894	1180
Phosphorus	ppm	ASTM D5185m	1150	1021	880	1109
Zinc	ppm	ASTM D5185m	1270	1278	1089	1347
Sulfur	ppm	ASTM D5185m	2060	3336	2998	3771
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	6	13	4
Sodium	ppm	ASTM D5185m		69	<u>▲</u> 252	49
Potassium	ppm	ASTM D5185m	>20	<1	4	2
Glycol	%	*ASTM D2982		NEG	0.0	NEG
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.7	0.5	0.8
Nitration	Abs/cm	*ASTM D7624	>20	9.1	9.5	10.1
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.4	19.7	22.7
FLUID DEGRAD	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.5	14.6	18.8
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	7.3	7.5	10.1
,						



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0084057 : 05935201

: 10620472

Received Diagnosed

: 29 Aug 2023 Diagnostician : Jonathan Hester

: 25 Aug 2023

Test Package : MOB 1 (Additional Tests: Glycol, TBN)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Kemp Quarries - Pryor Stone - Pryor

1050 E 520 Rd Pryor, OK US 74361

Contact: pryor@pryorstone.com

T:

F: