

PROBLEM SUMMARY

Sample Rating Trend

VISCOSITY

WISCOSITY


10432 KENWORTH T300

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (26 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

 Sample Status
 ATTENTION
 ATTENTION
 ATTENTION

 Visc @ 100°C
 cSt
 ASTM D445
 15.4
 ▲ 12.1
 ▲ 12.1
 ▲ 12.2

Customer Id: GFL001 Sample No.: GFL0094686 Lab Number: 05968710 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

13 Dec 2022 Diag: Jonathan Hester

VISCOSITY



No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.



13 Jun 2022 Diag: Angela Borella

VISCOSITY



No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.



07 Jan 2022 Diag: Jonathan Hester

VISCOSITY




No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.





OIL ANALYSIS REPORT

Sample Rating Trend



VISCOSITY



10432 KENWORTH T300

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (26 GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition


The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

	н <u>я</u> 2014 Feb.2015 Aug2015 Jul2016 Jul2017 Миу2019 Jun2012 Aug2012 Dec2022							
SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2		
Sample Number		Client Info		GFL0094686	GFL0052738	GFL0047948		
Sample Date		Client Info		02 Oct 2023	13 Dec 2022	13 Jun 2022		
Machine Age	hrs	Client Info		22600	211685	211685		
Oil Age	hrs	Client Info		0	320	336		
Oil Changed		Client Info		Not Changd	Changed	Changed		
Sample Status				ATTENTION	ATTENTION	ATTENTION		
CONTAMINATION	NC	method	limit/base	current	history1	history2		
Fuel		WC Method	>5	<1.0	<1.0	<1.0		
Glycol		WC Method		NEG	NEG	NEG		
WEAR METALS	3	method	limit/base	current	history1	history2		
Iron	ppm	ASTM D5185m	>100	5	21	12		
Chromium	ppm	ASTM D5185m	>20	<1	1	<1		
Nickel	ppm	ASTM D5185m	>2	0	0	0		
Titanium	ppm	ASTM D5185m	>2	0	0	0		
Silver	ppm	ASTM D5185m	>2	0	0	<1		
Aluminum	ppm	ASTM D5185m	>25	<1	2	2		
Lead	ppm	ASTM D5185m	>40	<1	<1	1		
Copper	ppm	ASTM D5185m	>330	<1	<1	<1		
Tin	ppm	ASTM D5185m	>15	0	<1	<1		
Antimony	ppm	ASTM D5185m						
Vanadium	ppm	ASTM D5185m		<1	0	0		
Cadmium	ppm	ASTM D5185m		0	0	0		
ADDITIVES		method	limit/base	current	history1	history2		
Boron	ppm	ASTM D5185m	0	3	18	11		
Barium	ppm	ASTM D5185m	0	0	0	0		
Molybdenum	ppm	ASTM D5185m	60	65	69	58		
Manganese	ppm	ASTM D5185m	0	<1	<1	<1		
Magnesium	ppm	ASTM D5185m	1010	1075	731	875		
Calcium	ppm	ASTM D5185m	1070	1199	1393	1088		
Phosphorus	ppm	ASTM D5185m	1150	1131	1027	995		
Zinc	ppm	ASTM D5185m	1270	1361	1214	1249		
Sulfur	ppm	ASTM D5185m	2060	3289	3645	3100		
CONTAMINANT	ΓS	method	limit/base	current	history1	history2		
Silicon	ppm	ASTM D5185m	>25	4	3	4		
Sodium	ppm	ASTM D5185m		6	2	1		
Potassium	ppm	ASTM D5185m	>20	<1	0	0		
INFRA-RED		method	limit/base	current	history1	history2		
Soot %	%	*ASTM D7844	>3	0.3	0.9	0.6		
Nitration	Abs/cm	*ASTM D7624	>20	5.2	8.0	6.6		
Sulfation	Abs/.1mm	*ASTM D7415		17.8	20.9	19.6		
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2		
Oxidation	Abs/.1mm	*ASTM D7414	>25	13.1	14.6	14.8		
	mg KOH/g		9.8	9.0	9.1	9.0		
= 3.50 · (abor (B.11)	9		0	0.0	0	0.0		



OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID FROF	LHILS	method	IIIIII/Dase	Current	HISTORY	Tilotoi y z
Visc @ 100°C	cSt	ASTM D445	15.4	12.1	<u> </u>	<u> </u>


GRAPHS

Ferrous Alloys













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0094686 : 05968710

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: 10675261

Received : 04 Oct 2023 Diagnosed : 06 Oct 2023 Diagnostician : Don Baldridge

GFL Environmental - 001 - Raleigh(CNG) 3741 Conquest Drive Garner, NC

US 27529 Contact: Craig Johnson craig.johnson@gflenv.com

T: (919)662-7100

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)662-7130