

PROBLEM SUMMARY

Sample Rating Trend


GLYCOL

829016-1067

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS			
Sample Status	ABNORMAL	ABNORMAL	SEVE

Sample Status

ABNORMAL ABNORMAL SEVERE

Potassium

ppm ASTM D5185m >20

232

382

2038

Customer Id: GFL659 Sample No.: GFL0090818 Lab Number: 05972081 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.
Check Glycol Access			?	We advise that you check for the source of the coolant leak.

HISTORICAL DIAGNOSIS

14 Aug 2023 Diag: Jonathan Hester

GLYCOL



We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend an early resample to monitor this condition. All component wear rates are normal. Sodium and/or potassium levels are high. The BN result indicates that there is suitable alkalinity remaining in the oil.



11 Jul 2023 Diag: Don Baldridge

GLYCOL



We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. All component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is positive. There is a high concentration of glycol present in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

view report

30 May 2023 Diag: Wes Davis

GLYCOL




We advise that you check for the source of the coolant leak. We recommend that you drain the oil from the component if this has not already been done. We advise that you flush the component thoroughly before re-filling with oil. We recommend an early resample to monitor this condition. All component wear rates are normal. Test for glycol is positive. There is a high concentration of glycol present in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.





OIL ANALYSIS REPORT

Sample Rating Trend



GLYCOL

A

829016-1067

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- LTR)

DIAGNOSIS

Recommendation

We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Sodium and/or potassium levels are high.


Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil.


.in)		Tay2020 Feb 20	21 Dec2021 Mar2022 Jul20	122 Feb2023 Apr2023 May2023 Ju	12023 Oct202	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0090818	GFL0090759	GFL0085090
Sample Date		Client Info		04 Oct 2023	14 Aug 2023	11 Jul 2023
Machine Age	hrs	Client Info		12119	11805	11661
Oil Age	hrs	Client Info		0	87594	0
Oil Changed		Client Info		N/A	N/A	Changed
Sample Status				ABNORMAL	ABNORMAL	SEVERE
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>110	11	13	34
Chromium	ppm	ASTM D5185m	>4	<1	<1	1
Nickel	ppm	ASTM D5185m	>2	<1	<1	0
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m	>2	<1	0	0
Aluminum	ppm	ASTM D5185m	>25	2	2	3
Lead	ppm	ASTM D5185m	>45	0	<1	2
Copper	ppm	ASTM D5185m	>85	8	13	54
Tin	ppm	ASTM D5185m	>4	0	0	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	5	10
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	87	102	295
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	1023	912	1021
Calcium	ppm	ASTM D5185m	1070	1079	1040	1179
Phosphorus	ppm	ASTM D5185m	1150	1127	1002	1051
Zinc	ppm	ASTM D5185m	1270	1413	1199	1330
Sulfur	ppm	ASTM D5185m	2060	3294	3301	3977
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>30	12	13	22
Sodium	ppm	ASTM D5185m		25	△ 50	<u>4</u> 248
Potassium	ppm	ASTM D5185m	>20	<u>232</u>	▲ 382	2 038
Glycol	%	*ASTM D2982		NEG	NEG	• 0.20
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.3	0.2	0.3
Nitration	Abs/cm	*ASTM D7624	>20	6.6	6.1	8.7
Sulfation	Abs/.1mm	*ASTM D7415	>30	18.8	18.3	22.7
FLUID DEGRAI	NOITAC	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	13.8	13.4	15.1
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	8.2	8.6	10.3
	9					



OIL ANALYSIS REPORT










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROPI	ERTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	13.8	13.9	13.9

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: 05972081 : 10684031

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0090818 Received Diagnosed

: 19 Oct 2023 Diagnostician : Doug Bogart

: 06 Oct 2023

Test Package : FLEET (Additional Tests: Glycol) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 659 - Mechanicsville

8280 RICHFOOD RD Mechanicsville, VA US 23116

Contact: Dwayne Oliver

dwayneoliver@gflenv.com

T: F: