

## **PROBLEM SUMMARY**



Machine Id **155** Component **Diesel Engine** Fluid **PETRO CANADA DURON SHP 10W30 (--- GAL)** 

#### COMPONENT CONDITION SUMMARY



#### RECOMMENDATION

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Sodium	ppm	ASTM D5185m		<u> </u>				

Customer Id: BLUCHA Sample No.: PCA0105197 Lab Number: 05980323 Test Package: FLEET



To manage this report scan the QR code

*To discuss the diagnosis or test data:* Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			
Resample			?	We recommend an early resample to monitor this condition.			
Check Glycol Access			?	We advise that you check for the source of the coolant leak.			

### HISTORICAL DIAGNOSIS



### **OIL ANALYSIS REPORT**

Sample Rating Trend



155 Component Diesel Engine Fluid

PETRO CANADA DURON SHP 10W30 (--- GAL)

#### DIAGNOSIS

Machine Id

#### Recommendation

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

#### Wear

All component wear rates are normal.

#### Contamination

Sodium and/or potassium levels are high.

#### Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0105197		
Sample Date		Client Info		04 Oct 2023		
Machine Age	mls	Client Info		115386		
Oil Age	mls	Client Info		27191		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINATI	ON	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	32		
Chromium	ppm	ASTM D5185m	>20	<1		
Nickel	ppm	ASTM D5185m	>4	<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>3	<1		
Aluminum	ppm	ASTM D5185m	>20	11		
Lead	ppm	ASTM D5185m	>40	0		
Copper	ppm	ASTM D5185m	>330	1		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	4		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	50	79		
Manganese	ppm	ASTM D5185m	0	<1		
Magnesium	ppm	ASTM D5185m	950	1013		
Calcium	ppm	ASTM D5185m	1050	1124		
Phosphorus	ppm	ASTM D5185m	995	1000		
Zinc	ppm	ASTM D5185m	1180	1368		
Sulfur	ppm	ASTM D5185m	2600	3049		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	11		
Sodium	ppm	ASTM D5185m		<u> </u>		
Potassium	ppm	ASTM D5185m	>20	20		
Glycol	%	*ASTM D2982		NEG		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.7		
Nitration	Abs/cm	*ASTM D7624	>20	9.9		
Sulfation	Abs/.1mm	*ASTM D7415	>30	21.2		
FLUID DEGRAD	<b>ATION</b>	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	17.1		
Base Number (BN)	mg KOH/a	ASTM D2896		7.6		
	9			-		



# **OIL ANALYSIS REPORT**









Certificate L2367

Laboratory

Sample No.

Lab Number

Unique Number

: PCA0105197

Test Package : FLEET (Additional Tests: Glycol)

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

: 05980323

: 10697618

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Received

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Diagnosed

Diagnostician

: 16 Oct 2023

: 18 Oct 2023

: Jonathan Hester

CHARLOTTE, NC

Contact: Jody Greer

T: (980)225-9968

F: (704)588-2901

1015 E. WESTINGHOUSE BLVD.

jgreer@bluemaxtrucking.com

US 28273