


PROBLEM SUMMARY


Area (54084Z) Walgreens - Tractor Machine Id [Walgreens - Tractor] 136A63404


Diesel Engine

PETRO CANADA DURON SHP 10W30 (11 GAL)

COMPONENT CONDITION SUMMARY







WEAR

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL			
Copper	ppm	ASTM D5185m	>150	<u> </u>	<u> </u>			

Sample Rating Trend

Customer Id: TSV1369 Sample No.: PCA0106585 Lab Number: 05986068 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		

HISTORICAL DIAGNOSIS



15 Apr 2023 Diag: Don Baldridge

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal. Elevated aluminum (AI) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.





OIL ANALYSIS REPORT

Oil Age

Fuel

Iron

Nickel

Silver

Lead

Tin

Copper

Titanium

Aluminum

Vanadium

Cadmium

Boron

Barium

Calcium

Zinc

Sulfur

Silicon

Sodium

Soot %

Nitration

Potassium

Chromium

Glycol

(54084Z) Walgreens - Tractor [Walgreens - Tractor] 136A63404

Diesel Engine

PETRO CANADA DURON SHP 10W30 (11 GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

A Wear

The copper level has decreased, but is still abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal.

Contamination

Elevated aluminum (AI) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. No other contaminants were detected in the oil.

Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.



Sulfation	Abs/.1mm	*ASTM D7415	>30	24.8	23.0	
FLUID DEGRAD	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	23.4	23.7	
Base Number (BN)	mg KOH/g	ASTM D2896		5.7	7.3	



OIL ANALYSIS REPORT



Contact/Location: Robert Beal - TSV1369