


PROBLEM SUMMARY






Machine Id 913078 Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (9 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	NORMAL	NORMAL	
Nickel	ppm	ASTM D5185m	>5	16	2	3	

Customer Id: GFL465 Sample No.: GFL0096517 Lab Number: 05996505 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

13 Aug 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



28 Jul 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



22 May 2023 Diag: Wes Davis

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT









Machine Id 913078 Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (9 GAL)

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

Exhaust valve wear is indicated. All other component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


The condition of the oil is acceptable for the time in service.


ON SHP 15W40 (GAL)	Dec2022	Mar2023 May2023	May2023 Jul2023 Aug2023	Oct2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0096517	GFL0087290	GFL0082727
Sample Date		Client Info		26 Oct 2023	13 Aug 2023	28 Jul 2023
Machine Age	hrs	Client Info		3012	2039	2427
Oil Age	hrs	Client Info		600	605	600
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	22	22	25
Chromium	ppm	ASTM D5185m	>20	1	1	<1
Nickel	ppm	ASTM D5185m	>5	1 6	2	3
Titanium	ppm	ASTM D5185m	>2	0	<1	<1
Silver	ppm	ASTM D5185m	>2	<1	0	0
Aluminum	ppm	ASTM D5185m	>20	<1	1	2
Lead	ppm	ASTM D5185m	>40	<1	1	<1
Copper	ppm	ASTM D5185m	>330	7	15	8
Tin	ppm	ASTM D5185m	>15	<1	1	<1
Vanadium	ppm	ASTM D5185m		0	<1	<1
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	2	1	<1
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	69	59	58
Manganese	ppm	ASTM D5185m	0	<1	1	<1
Magnesium	ppm	ASTM D5185m	1010	1035	968	948
Calcium	ppm	ASTM D5185m	1070	1226	1155	1063
Phosphorus	ppm	ASTM D5185m	1150	1102	985	942
Zinc	ppm	ASTM D5185m	1270	1335	1281	1186
Sulfur	ppm	ASTM D5185m	2060	3459	2993	2970
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	5	5	4
Sodium	ppm	ASTM D5185m		0	5	4
Potassium	ppm	ASTM D5185m	>20	2	3	<1
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>4	0.7	0.8	0.9
			0.0		0.4	0 =
Nitration	Abs/cm	*ASTM D7624	>20	8.1	8.4	8.7
	Abs/cm Abs/.1mm	*ASTM D7624 *ASTM D7415	>20	8.1 19.7	20.5	20.1
	Abs/.1mm	*ASTM D7415				
Sulfation FLUID DEGRAI	Abs/.1mm	*ASTM D7415	>30	19.7	20.5	20.1
Nitration Sulfation FLUID DEGRAI Oxidation Base Number (BN)	Abs/.1mm	*ASTM D7415 method	>30 limit/base >25	19.7 current	20.5 history1	20.1 history2



OIL ANALYSIS REPORT










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROP	EHILES	method	iiiiii/base	current	riistory i	HIStory
Visc @ 100°C	cSt	ASTM D445	15.4	13.8	13.7	13.6

GRAPHS













Laboratory Sample No. Lab Number **Unique Number**

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0096517 Received

: 05996505 : 10724865 Test Package : FLEET

: 02 Nov 2023

Diagnosed : 03 Nov 2023 Diagnostician : Sean Felton

888 Baldwin Pontiac, MI US 48340

GFL Environmental - 465 - Pontiac

Contact: Ricky Matthews rickymathews@gflenv.com T: (586)825-9514

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)