


# **PROBLEM SUMMARY**

Sample Rating Trend





426079-402318

Component **Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

# **COMPONENT CONDITION SUMMARY**





## RECOMMENDATION

We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE	SEVERE	SEVERE			
Fuel	%	ASTM D3524	>5	<b>11.4</b>	9.9	● 8.6			
Visc @ 100°C	cSt	ASTM D445	15.4	<b>11.0</b>	<b>▲</b> 11.8	▲ 12.1			

Customer Id: GFL836 Sample No.: GFL0095163 Lab Number: 06000308 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

#### **RECOMMENDED ACTIONS** Action **Status** Date Done By Description We recommend that you drain the oil from the component if this has not Change Fluid ? already been done. Resample We recommend an early resample to monitor this condition. Check Fuel/injector ? We advise that you check the fuel injection system. System

## HISTORICAL DIAGNOSIS

#### 20 Sep 2023 Diag: Wes Davis



We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.



#### 20 Jul 2023 Diag: Wes Davis





We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

# view report

#### 06 Jun 2023 Diag: Don Baldridge

FUEL




We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Cylinder, crank, or cam shaft wear is indicated. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.





# **OIL ANALYSIS REPORT**

Sample Rating Trend



Machine Id

**426079-402318**Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

# **DIAGNOSIS**

#### Recommendation

We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

## Wear

All component wear rates are normal.

## Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

#### ▲ Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Jun2019 Dec2019 May2020 May2023 Jun2023 Sep2023						
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0095163	GFL0090666	GFL0087157
Sample Date		Client Info		02 Nov 2023	20 Sep 2023	20 Jul 2023
Machine Age	hrs	Client Info		1935	1751	1551
Oil Age	hrs	Client Info		0	600	600
Oil Changed		Client Info		Not Changd	Changed	Changed
Sample Status				SEVERE	SEVERE	SEVERE
CONTAMINAT	ION	method	limit/base	current	history1	history2
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	19	29	38
Chromium	ppm	ASTM D5185m	>20	<1	2	2
Nickel	ppm	ASTM D5185m	>4	<1	<1	<1
Titanium	ppm	ASTM D5185m		<1	0	<1
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>20	2	4	2
Lead	ppm	ASTM D5185m	>40	<1	<1	<1
Copper	ppm	ASTM D5185m	>330	3	8	7
Tin	ppm	ASTM D5185m	>15	<1	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	2	<1	0
Barium	ppm	ASTM D5185m	0	5	0	0
Molybdenum	ppm	ASTM D5185m	60	57	57	61
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	823	870	947
Calcium	ppm	ASTM D5185m	1070	948	964	1034
Phosphorus	ppm	ASTM D5185m	1150	916	900	950
Zinc	ppm	ASTM D5185m	1270	1085	1138	1183
Sulfur	ppm	ASTM D5185m	2060	2653	2711	3116
CONTAMINAN	IIS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	6	4	4
Sodium	ppm	ASTM D5185m		0	5	8
Potassium	ppm	ASTM D5185m	>20	3	5	<1
Fuel	%	ASTM D3524		11.4	9.9	8.6
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.7	0.9	1.1
Nitration	Abs/cm	*ASTM D7624		10.8	10.9	12.0
Sulfation	Abs/.1mm	*ASTM D7415	>30	23.3	22.3	23.3
FLUID DEGRAI	NOITAC	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	24.0	21.0	21.5
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	6.0	6.2	7.2



# OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: GFL0095163 : 06000308 : 10728668

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Nov 2023 Diagnosed

: 08 Nov 2023 Diagnostician : Wes Davis

Test Package : FLEET ( Additional Tests: PercentFuel ) To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 836 - Kansas City Hauling

7801 East Truman Road Kansas City, MO US 64126

Contact: Robert Hart rhart@gflenv.com T: (580)461-1509