


PROBLEM SUMMARY


PROCESS CHEESE [98620100] Machine Id AUGER CART 2 EAST

Component Gearbox

GEAR OIL ISO 220 (--- GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

The oil change at the time of sampling has been noted. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL					
Particles >4µm	ASTM D7647 >1300	<u> </u>	<u>▲</u> 126028						
Particles >6µm	ASTM D7647 >320	42573	△ 35697						
Particles >14µm	ASTM D7647 >80	2268	<u> </u>						
Particles >38μm	ASTM D7647 >4	<u> </u>	<u> </u>						
Oil Cleanliness	ISO 4406 (c) >17/15	5/13 🔺 24/23/18	<u>4</u> 24/22/18						

Customer Id: KRASPRMO Sample No.: PCA0101660 Lab Number: 06001551 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component if applicable.

HISTORICAL DIAGNOSIS

28 Jan 2023 Diag: Don Baldridge

ISO



The oil change at the time of sampling has been noted. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



15 Jan 2022 Diag: Don Baldridge

VISUAL METAL



The oil change at the time of sampling has been noted. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample. Moderate concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. The AN level is acceptable for this fluid.



19 Jun 2021 Diag: Jonathan Hester

VISUAL METAL



The oil change at the time of sampling has been noted. We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample. Moderate concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. The AN level is acceptable for this fluid.






OIL ANALYSIS REPORT

PROCESS CHEESE [98620100] **AUGER CART 2 EAST**

Component

Gearbox

GEAR OIL ISO 220 (--- GAL)





DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		Nov2020	Jun2021	Jan 2022 Jan 2023	Oct2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0101660	PCA0081532	PCA0065324
Sample Date		Client Info		30 Oct 2023	28 Jan 2023	15 Jan 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	10	6	6
Chromium	ppm	ASTM D5185m	>15	<1	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	2	0	2
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	0	0	<1
Tin	ppm	ASTM D5185m	>25	0	0	0
Antimony	ppm	ASTM D5185m	>5			<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	50	0	0	<1
Barium	ppm	ASTM D5185m	15	0	0	0
Molybdenum	ppm	ASTM D5185m	15	0	0	0
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m	50	<1	<1	0
Calcium	ppm	ASTM D5185m	50	1	<1	0
Phosphorus	ppm	ASTM D5185m	350	488	393	187
Zinc	ppm	ASTM D5185m	100	0	<1	0
Sulfur	ppm	ASTM D5185m	12500	1207	1103	224
CONTAMINAN [*]	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	12	8	19
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	1	<1	0
FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>1300	123089	<u>126028</u>	
Particles >6µm		ASTM D7647	>320	42573	△ 35697	
Particles >14µm		ASTM D7647	>80	2268	▲ 1366	
Particles >21µm		ASTM D7647	>20	476	<u>▲</u> 232	
Particles >38µm		ASTM D7647	>4	<u> </u>	△ 3	
Particles >71µm		ASTM D7647	>3	1	0	
Oil Cleanliness		ISO 4406 (c)	>17/15/13	<u>4</u> 24/23/18	<u>△</u> 24/22/18	
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
	140114	4 OT1 4 DOG 4 5				

Acid Number (AN)

mg KOH/g ASTM D8045 0.85

0.54

0.54

0.41



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0101660 : 06001551

: 10729911

: 08 Nov 2023 Received Diagnosed : 09 Nov 2023 Diagnostician

: Angela Borella

Test Package : IND 2 (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

KraftHeinz - Springfield - Plant 8311 PCA

2035 E BENNETT SPRINGFIELD, MO

US 65804

Contact: Service Manager

T: F: